



---

**PRODUCT BULLETIN # 20248**Generic Copy

---

**Issue Date:** 10-Oct-2013**TITLE:** LC72715 Datasheet Update**PROPOSED FIRST SHIP DATE:** 10-Jan-2014 or sooner on customer approval**AFFECTED CHANGE CATEGORY(S):** Datasheet Only**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**

Contact your local ON Semiconductor sales office or  
Kazuhiro Nakamuta <Kazuhiro.Nakamuta@onsemi.com>

**NOTIFICATION TYPE:**

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact <quality@onsemi.com>.

**DESCRIPTION AND PURPOSE:**

Several corrections are made with the publication of the revision 1.23 of the LC72715 datasheet.

- Correction of errors:
  - Timing parameter of CPU interface: tDD $\bar{O}$  minimum and maximum time are changed to 135ns and 320ns respectively. (originally 277ns and 555ns respectively)
  - tDD $\bar{O}$ 2 minimum time is changed to 135ns. (originally 140ns)
  - The explanation of the CPU register "Number of allowable BIC errors": BIC\_F (Forward protection value) is changed to bit7-4. (originally bit3-0) and BIC\_B (Backward protection value) is changed to bit3-0 (originally bit7-4). BIC\_F and BIC\_B are replaced for correcting error.
  - The table of "List of operation modes": When "mode 2" is set, the NG data of vertically-corrected output is "not output". (originally "output")
- Additional Information:
  - The name of the VICS Center : The official name "Vehicle Information and Communication System Center" is added.
  - The name of the NHK Engineering Service: The organization name is changed to NHK Engineering System, Inc.
  - The explanation of the CPU register "Control register 1": Additional information of DO\_MOVE is added. Besides the figure of the relationship between INT and DO is added.
  - The explanation of the CPU register "Status register" and "Block Number register": Additional information of the value in the "Reset" column is added.
  - The explanation of the register read timing: The condition when the status register can be read in a manner asynchronous with INT is only when INT\_MOVE is set to "1".

**List of affected General Parts:**

LC72717PW-H



**PRODUCT BULLETIN #20248**

**List of affected Customer Specific Parts:**

LC72715PW-UONK-TLM-H  
LC72715PW-UF-H  
LC72715PW-UJK-H  
LC72715PW-SH-UD-H  
LC72715PW-UP-H  
LC72715W-UGAR-TLM-H  
LC72715LG-UM-TLM-H  
LC72715PW-TLM-H  
LC72715LG-TLM-H  
LC72715PLG-H  
LC72715PW-H