



---

**PRODUCT BULLETIN # 20510**

Generic Copy

---

**Issue Date:** 12-Jun-2014

**TITLE:** NCP81022: Power On reset block modification

**PROPOSED FIRST SHIP DATE:** 12-Sep-2014

**AFFECTED CHANGE CATEGORY(S):** Die Part Change

**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**

Contact your local ON Semiconductor sales office or <[raymond.odell@onsemi.com](mailto:raymond.odell@onsemi.com)>

**NOTIFICATION TYPE:**

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact <[quality@onsemi.com](mailto:quality@onsemi.com)>.

**DESCRIPTION AND PURPOSE:**

To eliminate the possibility of an incorrect Power On reset, under high power supply slew rate conditions.

The solution was to bypass a redundant flip flop. This was an internal housekeeping signal only and did not have any impact on the functionality of the part.

The modification was implemented with a single layer metal mask change on the die.

No functionality or specification change with no change to the datasheet and no subsequent impact to the customer.

**List of affected General Parts:**

NCP81022MNTXG