



FINAL PRODUCT/PROCESS CHANGE NOTIFICATION #20324J-AGeneric Copy

Issue Date: 30-May-2014**TITLE:** Test site transfer from Kanto Sanyo Semiconductors Co., Ltd to ON Semiconductor SSMP Philippines Corporation (Group10-A)**PROPOSED FIRST SHIP DATE:** 30-Aug-2014 (or earlier upon approval due to shortage of product)**AFFECTED CHANGE CATEGORY(S):** Test site**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**

Contact your local ON Semiconductor Sales Office or

<toshiitsu.igarashi@onsemi.com><takeshi2.hoshino@onsemi.com> <shinya.okada@onsemi.com>
<ikuo.saeaki@onsemi.com><Toshimitsu.Namiki@onsemi.com><naoki.koyama@onsemi.com>
<takehito.tsukui@onsemi.com> <keiji.ueda@onsemi.com>

SAMPLES: Contact your local ON Semiconductor Sales Office or <Takakshi.Asami@onsemi.com>**ADDITIONAL RELIABILITY DATA:** Not Available**NOTIFICATION TYPE:**

Final Product/Process Change Notification (FPCN)

Final change notification sent to customers. FPCNs are issued at least 90 days prior to implementation of the change.

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

As a part of restructuring of semiconductor production infrastructure, Hanyu plant of Kanto Sanyo Semiconductors Co., Ltd will be closed at the end of June, 2014 and have been started preparation for end of production.

In order to continue supply of applicable products under this condition, the products and the equipments will be transferred to ON Semiconductor SSMP Philippines Corporation.

**FINAL PRODUCT/PROCESS CHANGE NOTIFICATION #20324J-A****RELIABILITY DATA SUMMARY:**

There is no reliability data for only test site transfer.

ELECTRICAL CHARACTERISTIC SUMMARY:

There is no change in the electrical performance. Datasheet specifications remain unchanged.

CHANGED PART IDENTIFICATION:

Products manufactured at SSMP will be marked with 'L7' preceding the Serial No. on shipping label.

List of affected General Parts: Group10-A

LA1070-MPB-E
LC823425-12G1-H
LC823425-12G1-LR-H
LC823425-12G-H
LC823430TA-2H
LC823431TAK-2H
LC823432TAK-2H
LC87F5864CUTG2H
LC89058WA-E
LC898201TA-NH
LV52204MTTBG
LV52204MUTBG
LV52205MUTBG

List of affected Customer Specific Parts: Group10-A

1410010-MPB-E
1410010-TRM-E
LC24006G-15C-H
LC74772V-9881-TLM-E
LC823420S-12AS-H
LC87F5864CF58F1TG-2H
LC87F9W48A-F5CD1-H
LC87F9W48A-F5CD3-H
LC98500DQ-13P-H
LC98600CT-11J-H
LC98800DF-14A-H