

FINAL PRODUCT/PROCESS CHANGE NOTIFICATION #20324H-A

Generic Copy

Issue Date: 05-Apr-2014

TITLE: Test site transfer from Kanto Sanyo Semiconductors Co., Ltd to ON Semiconductor SSMP Philippines Corporation (Group 09-A)

PROPOSED FIRST SHIP DATE: 05-Jul-2014

AFFECTED CHANGE CATEGORY(S): Test site

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or

<toshiitsu.igarashi@onsemi.com><takeshi2.hoshino@onsemi.com> <shinya.okada@onsemi.com> <ikuo.saeki@onsemi.com><Toshimitsu Namiki@onsemi.com ><naoki.koyama@onsemi.com> <takehito.tsukui@onsemi.com> <keiji.ueda@onsemi.com>

SAMPLES: Contact your local ON Semiconductor Sales Office or<Takashi.Asami@onsemi.com>

ADDITIONAL RELIABILITY DATA: Not Available

NOTIFICATION TYPE:

Final Product/Process Change Notification (FPCN)

Final change notification sent to customers. FPCNs are issued at least 90 days prior to implementation of the change.

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

As a part of restructuring of semiconductor production infrastructure, Hanyu plant of Kanto Sanyo Semiconductors Co., Ltd will be closed at the end of June, 2014 and have been started preparation for end of production.

In order to continue supply of applicable products under this condition, the products and the equipments will be transferred to ON Semiconductor SSMP Philippines Corporation.

Issue Date: 05-Apr-2014 Rev. 06-Jan-2010 Page 1 of 3



FINAL PRODUCT/PROCESS CHANGE NOTIFICATION #20324H-A

RELIABILITY DATA SUMMARY:

There is no reliability data for only test site transfer.

ELECTRICAL CHARACTERISTIC SUMMARY:

There is no change in the electrical performance. Datasheet specifications remain unchanged.

CHANGED PART IDENTIFICATION:

Products manufactured at SSMP will be marked with 'L7' preceding the Serial No. on shipping label.

List of affected General Parts: Group09-A

LC749402BG-TLM-H

LC822973-10B-E

LC823170PRA-4H

LC823175PRA-4H

LC823402A-06C-16LR-E

LC823403A-08A5-16-E

LC823403B-08B3-E

LC823403B-08B-E

LC823425-13W1-E

LC823425-13W1-LR-E

LC823425-13W-E

LC823425-14S1-E

LC823491-12M-220E

LC82360G-YJ2-E

LC898107A-TBM-H

LC898108A-N-TBM-H

LC898108B-TBM-H

LC898109-N-TBM-H

LC898110A-TBM-H

LC898200A-TBM-H

LC898200B-TBM-H

LC898201RA-NH

Issue Date: 05-Apr-2014 Rev. 06-Jan-2010 Page 2 of 3



FINAL PRODUCT/PROCESS CHANGE NOTIFICATION #20324H-A

List of affected Customer Specific Parts: Group09-A

LC272J7DT-16J-H

LC74156PB-E

LC74156PB-UC-E

LC74156PNB-SH-UC-E

LC74156PNB-SH-UD-E

LC74156PNB-SH-UKW-E

LC74156PNB-SH-UTS-E

LC74157PBG-SH-E

LC74157PBG-SH-UC-E

LC74157PBG-SH-UD-E

LC74157PBG-SH-UP-E

LC74157PBG-SH-UTS-E

LC749402BG-UTS-TLM-H

LC79450BG-UCZ-E

LC822973-04VM-TBMGBE

LC822973-10BA-E

LC823402-03H-16-E

LC823403-07M3-16-E

LC823411-12L1-H

LC88F5LA4A2304TE-L-H

LC88F5LA4A2305TE-L-H

LC88F5LA4A-F2313-MH

LC98500BT-03FA-H

LC99461-13Z-4H

Issue Date: 05-Apr-2014 Rev. 06-Jan-2010 Page 3 of 3