



Subject: Motorola PRODUCT BULLETIN 4594

TITLE: SECTOR MATERIALS ORGANIZATION (SMO) CLOSURE (PART 6 OF 8)

EFFECTIVE DATE: 05-APR-99

AFFECTED CHANGE CATEGORIES

AFFECTED PRODUCT DIVISIONS

GENERAL PURPOSE PRO POWER PRODUCTS DIV OPTO SIGNAL DIV

ADDITIONAL RELIABILITY DATA: None Ref:

SAMPLES: No Ref:

For any questions concerning this notification:

REFERENCE: ED BRZEZINSKI PHONE: 602-244-4575

DISCLAIMER:

MOTOROLA CONSIDERS THIS CHANGE APPROVED UNLESS SPECIFIC CONDITIONS OF ACCEPTANCE ARE PROVIDED IN WRITING. TO DO SO, CONTACT YOUR LOCAL MOTOROLA SALES OFFICE.

GPCN FORMAT: CUSTOMER

DO NOT REPLY TO THIS MESSAGE.

PRODUCT BULLETIN

ISSUE DATE: 10-Apr-1999

NOTIFICATION #:4594

EFFECTIVE DATE: 05-Apr-1999

ISSUING DIVISION:PHX-PPD

DESCRIPTION AND PURPOSE

*****ATTENTION*****
This Product Bulletin (PB) is part of eight PBs covering the Sector Materials Organization Closure. This was originally intended to be released on one PB, but due to size limitations, it had to be divided by technology codes. Some customers may receive what appears to be the same PB multiple times, but the device list will be different on each PB: 4575, 4590, 4591, 4592, 4593, 4594, 4595 and 4596.

Motorola Semiconductor Products Sector is currently going through realignment of its manufacturing resources. The Silicon Materials Organization (SMO) in Phoenix, Arizona, originally opened in 1958, and is currently scheduled to be closed by the end of June 1999. Silicon wafers currently provided by this facility will transfer to previously qualified sources or to Mitsubishi Silicon America's (MSA) production facility at its headquarters in Salem, Oregon. MSA, one of the top six global silicon materials suppliers, was chosen for its global technological and logistic capabilities. MSA has been an approved silicon supplier to Motorola for over 5 years. The transfer will occur after significant technology transfer and Motorola internal evaluation and qualification. This qualification process has been designed to help make the transfer seamless to our customers.

FILE FORMAT: ASCII TEXT
FONT - Courier
SIZE - 12 Point
LINE - 70 characters/line
PAGE - 55 lines/page
PAGEBREAK CHARACTER - ^L (Control L)

AFFECTED DEVICE LIST (WITHOUT SPECIALS)

1N4370A	,	1N4370ARL	,	1N4371A	,	1N4371ARL
1N4371ATA	,	1N4372A	,	1N4372ARL	,	1N4372ATA
1N4626RL	,	1N4678	,	1N4678RL	,	1N4679RL
1N4680	,	1N4681	,	1N4681CRL	,	1N4681RL
1N4682	,	1N4682RL	,	1N4683	,	1N4683CRL
1N4683RL	,	1N4684	,	1N4684RL	,	1N4685
1N4685RA1	,	1N4685RL	,	1N4686	,	1N4686RL
1N4687	,	1N4687CRL	,	1N4687RL	,	1N4688
1N4688RL	,	1N4689	,	1N4689CRL	,	1N4689RL
1N4689TA	,	1N4690	,	1N4690RL	,	1N4691
1N4691CRA1	,	1N4691RL	,	1N4692	,	1N4692RL
1N4693	,	1N4693RL	,	1N4694	,	1N4694RL
1N4695	,	1N4695RL	,	1N4696	,	1N4696CRL
1N4696RL	,	1N4697	,	1N4697RL	,	1N4698
1N4698RL	,	1N4699	,	1N4699CRL	,	1N4699D
1N4699RL	,	1N4700	,	1N4700RL	,	1N4701
1N4701RL	,	1N4702	,	1N4702RL	,	1N4702TA
1N4702TA2	,	1N4703RL	,	1N4704RL	,	1N4705
1N4705RL	,	1N4707CRL	,	1N4707RL	,	1N4708RL
1N4711RL	,	1N4713	,	1N5221B	,	1N5221BRL
1N5222B	,	1N5222BRL	,	1N5223B	,	1N5223BRL
1N5223BTA	,	1N5223BTA2	,	1N5224BRL	,	1N5225B
1N5225BRL	,	1N5226B	,	1N5226BRL	,	1N5226BTA
1N5226C	,	1N5226D	,	1N5227B	,	1N5227BRL
1N5227BTA	,	1N5228B	,	1N5228BRL	,	1N5228BTA
1N5228BTA2	,	1N5229B	,	1N5229BRL	,	1N5230B
1N5230BRL	,	1N5230BS	,	1N5230BSRL	,	1N5230BTA
1N5230BTA2	,	1N5231B	,	1N5231BRA1	,	1N5231BRL
1N5231BRR2	,	1N5231BS	,	1N5231BSRL	,	1N5231BTA
1N5231CRL	,	1N5231D	,	1N5231DRL	,	1N5232B
1N5232BRL	,	1N5232BS	,	1N5232BSRL	,	1N5232BTA
1N5232CRL	,	1N5232DRL	,	1N5233B	,	1N5233BRL
1N5233D	,	1N5234B	,	1N5234BRL	,	1N5234BRR1
1N5234BS	,	1N5234BSRL	,	1N5234CRL	,	1N5234DRL
1N5235B	,	1N5235BRL	,	1N5235BS	,	1N5235BSRL
1N5235BTA	,	1N5236B	,	1N5236BRL	,	1N5236BTA2
1N5236CRL	,	1N5236D	,	1N5237B	,	1N5237BRL
1N5237BRR1	,	1N5237C	,	1N5238B	,	1N5238BRL
1N5239B	,	1N5239BRL	,	1N5239BTA	,	1N5239C
1N5239CRL	,	1N5239D	,	1N5239DRL	,	1N5240B
1N5240BRL	,	1N5240BS	,	1N5240BTA	,	1N5240CRL
1N5240DRL	,	1N5241B	,	1N5241BRL	,	1N5241CRL
1N5242B	,	1N5242BRL	,	1N5243B	,	1N5243BRL
1N5243BTA	,	1N5244B	,	1N5244BRA2	,	1N5244BRL
1N5245B	,	1N5245BRL	,	1N5245BTA	,	1N5245CRL
1N5246B	,	1N5246BRA1	,	1N5246BRL	,	1N5246CRL
1N5246DRL	,	1N5247B	,	1N5247BRL	,	1N5247BTA
1N5248B	,	1N5248BRL	,	1N5248BTA	,	1N5248DRL
1N5249B	,	1N5249BRL	,	1N5250B	,	1N5250BRL
1N5251B	,	1N5251BRL	,	1N5252B	,	1N5252BRL
1N5252BRL2	,	1N5252BTA	,	1N5253B	,	1N5253BRL
1N5253BTA	,	1N5254B	,	1N5254BRL	,	1N5254BTA
1N5255B	,	1N5255BRL	,	1N5255BTA	,	1N5256B
1N5256BRL	,	1N5256BTA	,	1N5256CRL	,	1N5257B
1N5257BRL	,	1N5257BTA	,	1N5258B	,	1N5258BRL
1N5258BTA	,	1N5258CRL	,	1N5259B	,	1N5259BRL
1N5259BTA	,	1N5259BTA2	,	1N5259CRL	,	1N5260B
1N5260BRL	,	1N5260BTA	,	1N5261B	,	1N5261BRL

PRODUCT BULLETIN

ISSUE DATE: 10-Apr-1999
EFFECTIVE DATE: 05-Apr-1999

NOTIFICATION #:4594
ISSUING DIVISION:PHX-PPD

1N5261BTA	,	1N5262B	,	1N5262BRL	,	1N5262BTA
1N5263B	,	1N5263BRL	,	1N5263BTA	,	1N5264BRL
1N5264BTA	,	1N5265B	,	1N5265BRL	,	1N5266B
1N5266BRL	,	1N5267B	,	1N5267BRL	,	1N5268B
1N5269BRL	,	1N5270B	,	1N5270BRL	,	1N5270CRL
1N5271B	,	1N5271BRL	,	1N5271DRL	,	1N5272B
1N5272BRL	,	1N5273BRL	,	1N5273CRL	,	1N5274B
1N5274BRL	,	1N5275B	,	1N5275BRL	,	1N5275CRL
1N5275DRL	,	1N5276BRL	,	1N5278B	,	1N5278BRL
1N5279B	,	1N5279BRL	,	1N5280BRL	,	1N5281B
1N5281BRL	,	1N5283	,	1N5283RL	,	1N5287
1N5287RL	,	1N5297	,	1N5297RL	,	1N5298
1N5298RL	,	1N5305	,	1N5307	,	1N5309
1N5309RL	,	1N5310	,	1N5311	,	1N5311RL
1N5312	,	1N5312RL	,	1N5314	,	1N5314RL
1N5333B	,	1N5333BRL	,	1N5334B	,	1N5334BRL
1N5335B	,	1N5335BRL	,	1N5336B	,	1N5336BRL
1N5337B	,	1N5337BRL	,	1N5338B	,	1N5338BRL
1N5338C	,	1N5339B	,	1N5339BRL	,	1N5340B
1N5340BRL	,	1N5341B	,	1N5341BRL	,	1N5342B
1N5342BRL	,	1N5343B	,	1N5343BRL	,	1N5344B
1N5344BRL	,	1N5345B	,	1N5345BRL	,	1N5345CRL
1N5346B	,	1N5346BRL	,	1N5347B	,	1N5347BRL
1N5348B	,	1N5348BRL	,	1N5349B	,	1N5349BRL
1N5350B	,	1N5350BRL	,	1N5351B	,	1N5351BRL
1N5352B	,	1N5352BRL	,	1N5353B	,	1N5353BRL
1N5354B	,	1N5354BRL	,	1N5355B	,	1N5355BRL
1N5356B	,	1N5356BRL	,	1N5357B	,	1N5357BRL
1N5358B	,	1N5358BRL	,	1N5359B	,	1N5359BRL
1N5359CRL	,	1N5360B	,	1N5360BRL	,	1N5361B
1N5361BRL	,	1N5361BTA	,	1N5362B	,	1N5362BRL
1N5363B	,	1N5363BRL	,	1N5364B	,	1N5364BRL
1N5365B	,	1N5365BRL	,	1N5366B	,	1N5366BRL
1N5367B	,	1N5367BRL	,	1N5368B	,	1N5368BRL
1N5369B	,	1N5369BRL	,	1N5370B	,	1N5370BRL
1N5371B	,	1N5371BRL	,	1N5372B	,	1N5372BRL
1N5373B	,	1N5373BRL	,	1N5374B	,	1N5374BRL
1N5375B	,	1N5375BRL	,	1N5376B	,	1N5376BRL
1N5377B	,	1N5377BRL	,	1N5378B	,	1N5378BRL
1N5379B	,	1N5379BRL	,	1N5380B	,	1N5380BRL
1N5381B	,	1N5381BRL	,	1N5382B	,	1N5382BRL
1N5383B	,	1N5383BRL	,	1N5384B	,	1N5384BRL
1N5385B	,	1N5385BRL	,	1N5386B	,	1N5386BRL
1N5387B	,	1N5387BRL	,	1N5388B	,	1N5388BRL
1N5985BRL	,	1N5987B	,	1N5988B	,	1N5988BRL
1N5989BRL	,	1N5990B	,	1N5990BRL	,	1N5990CRL
1N5991BRL	,	1N5992B	,	1N5992BRL	,	1N5992BS
1N5992BSRL	,	1N5992DRL	,	1N5993B	,	1N5993BRL
1N5993D	,	1N5993DRL	,	1N5994B	,	1N5994BRL
1N5994BS	,	1N5994BSRL	,	1N5995B	,	1N5995BRL
1N5995CRL	,	1N5996B	,	1N5996BRL	,	1N5996BS

PRODUCT BULLETIN

ISSUE DATE: 10-Apr-1999
EFFECTIVE DATE: 05-Apr-1999

NOTIFICATION #:4594
ISSUING DIVISION:PHX-PPD

1N5996BSRL	,	1N5997BRL	,	1N5998B	,	1N5998BRL
1N5999BRL	,	1N6000B	,	1N6001BRL	,	1N6002B
1N6004B	,	1N6004BRL	,	1N6007BRL	,	1N6013BS
1N6013BSRL	,	1N6025CRL	,	1N746A	,	1N746ARL
1N746AS	,	1N746ASRL	,	1N746ASTA	,	1N746ATA
1N747A	,	1N747ARL	,	1N747ASTA	,	1N747ATA
1N748A	,	1N748ARL	,	1N748ASRL	,	1N748ASTA
1N749A	,	1N749ARL	,	1N749ASTA	,	1N749ATA
1N749DRL	,	1N750A	,	1N750ARL	,	1N750ASRL
1N750ASTA	,	1N750ATA	,	1N750D	,	1N750DRL
1N751A	,	1N751ARL	,	1N751AS	,	1N751ASRL
1N751ASTA	,	1N751ATA	,	1N751CRL	,	1N751D
1N751DRL	,	1N752A	,	1N752ARL	,	1N752AS
1N752ASRL	,	1N752ASTA	,	1N752ATA	,	1N752C
1N752CRL	,	1N753A	,	1N753ARL	,	1N753AS
1N753ASRL	,	1N753ASTA	,	1N753ATA	,	1N753DRL
1N754A	,	1N754ARL	,	1N754ASRL	,	1N754ASTA
1N754ATA	,	1N755A	,	1N755ARL	,	1N755ASRL
1N755ASTA	,	1N755ATA	,	1N756A	,	1N756ARL
1N756AS	,	1N756ASRL	,	1N756ASTA	,	1N756ATA
1N757A	,	1N757ARL	,	1N757ASRL	,	1N757ASTA
1N757ATA	,	1N758A	,	1N758ARL	,	1N758ATA
1N759A	,	1N759ARL	,	1N759ATA	,	1N821
1N821A	,	1N821ARL	,	1N821RL	,	1N823
1N823A	,	1N823ARL	,	1N823RL	,	1N825
1N825A	,	1N825ARL	,	1N825RL	,	1N827
1N827A	,	1N827ARL	,	1N827RL	,	1N829
1N829A	,	1N829ARL	,	1N829RL	,	1N957B
1N958B	,	1N959B	,	1N960B	,	1N960BRL
1N961B	,	1N961BRL	,	1N961BRR1	,	1N961CRL
1N962B	,	1N962BRL	,	1N962BTA	,	1N963B
1N963BRL	,	1N963BRR1	,	1N963BTA	,	1N964B
1N964BRL	,	1N964BTA	,	1N965B	,	1N965BRL
1N965BTA	,	1N966B	,	1N966BRL	,	1N966BTA
1N967B	,	1N967BRL	,	1N967BTA	,	1N968B
1N968BRL	,	1N969BRL	,	1N970BRL	,	1N971BRL
1N971BTA	,	1N972BRL	,	1N972BTA	,	1N973BRL
1N974BRL	,	1N974BTA	,	1N975BRL	,	1N978B
1N979BRL	,	1N982BRL	,	1N986BRL	,	1N989B
1N990BRL	,	1N991BRL	,	1SMA10AT3	,	1SMA10CAT3
1SMA11AT3	,	1SMA11CAT3	,	1SMA12AT3	,	1SMA12CAT3
1SMA13CAT3	,	1SMA14CAT3	,	1SMA15AT3	,	1SMA15CAT3
1SMA16AT3	,	1SMA16CAT3	,	1SMA17AT3	,	1SMA17CAT3
1SMA18AT3	,	1SMA18CAT3	,	1SMA20AT3	,	1SMA20CAT3
1SMA22AT3	,	1SMA22CAT3	,	1SMA24AT3	,	1SMA24CAT3
1SMA26AT3	,	1SMA26CAT3	,	1SMA28AT3	,	1SMA28CAT3
1SMA30AT3	,	1SMA30CAT3	,	1SMA33AT3	,	1SMA33CAT3
1SMA36AT3	,	1SMA36CAT3	,	1SMA40AT3	,	1SMA40CAT3
1SMA43AT3	,	1SMA43CAT3	,	1SMA45AT3	,	1SMA45CAT3
1SMA48AT3	,	1SMA48CAT3	,	1SMA5.0AT3	,	1SMA51AT3
1SMA51CAT3	,	1SMA54AT3	,	1SMA54CAT3	,	1SMA58AT3

PRODUCT BULLETIN

ISSUE DATE: 10-Apr-1999
EFFECTIVE DATE: 05-Apr-1999

NOTIFICATION #:4594
ISSUING DIVISION:PHX-PPD

1SMA58CAT3	,	1SMA5913BT3	,	1SMA5914BT3	,	1SMA5915BT3
1SMA5916BT3	,	1SMA5917BT3	,	1SMA5918BT3	,	1SMA5919BT3
1SMA5920BT3	,	1SMA5921BT3	,	1SMA5922BT3	,	1SMA5923BT3
1SMA5924BT3	,	1SMA5925BT3	,	1SMA5926BT3	,	1SMA5927BT3
1SMA5928BT3	,	1SMA5929BT3	,	1SMA5930BT3	,	1SMA5931BT3
1SMA5932BT3	,	1SMA5933BT3	,	1SMA5934BT3	,	1SMA5935BT3
1SMA5936BT3	,	1SMA5937BT3	,	1SMA5938BT3	,	1SMA5939BT3
1SMA5940BT3	,	1SMA5941BT3	,	1SMA5942BT3	,	1SMA5943BT3
1SMA5944BT3	,	1SMA5945BT3	,	1SMA6.0AT3	,	1SMA6.5AT3
1SMA60AT3	,	1SMA60CAT3	,	1SMA64AT3	,	1SMA64CAT3
1SMA7.0AT3	,	1SMA7.5AT3	,	1SMA70AT3	,	1SMA70CAT3
1SMA75AT3	,	1SMA75CAT3	,	1SMA78CAT3	,	1SMA8.0AT3
1SMA8.5AT3	,	1SMA9.0AT3	,	BZX55B5V1RL	,	BZX55B5V6RL
BZX55C10RL	,	BZX55C12RL	,	BZX55C15RL	,	BZX55C2V7RL
BZX55C3V0RL	,	BZX55C3V3RL	,	BZX55C3V6RL	,	BZX55C3V9RL
BZX55C4V3RL	,	BZX55C4V7RL	,	BZX55C5V1RL	,	BZX55C5V6RL
BZX55C6V2RL	,	BZX55C6V8RL	,	BZX55C7V5RL	,	BZX55C8V2RL
BZX55C9V1RL	,	BZX79B6V2RL	,	BZX79B6V8RL	,	BZX79C10RL
BZX79C12RL	,	BZX79C15RL	,	BZX79C16RL	,	BZX79C18RL
BZX79C22RL	,	BZX79C24RL	,	BZX79C27RL	,	BZX79C2V4RL
BZX79C2V7RL	,	BZX79C30RL	,	BZX79C33RL	,	BZX79C3V0RL
BZX79C3V3RL	,	BZX79C3V6RL	,	BZX79C3V9RL	,	BZX79C4V7RL
BZX79C5V1RL	,	BZX79C5V6RL	,	BZX79C6V2RL	,	BZX79C6V8RL
BZX79C7V5RL	,	BZX79C8V2RL	,	LMB43CL1WP	,	MZ4614
MZ4614RL	,	MZ4615	,	MZ4615RL	,	MZ4616
MZ4617RL	,	MZ4618	,	MZ4619	,	MZ4619RL
MZ4620	,	MZ4620RL	,	MZ4622RL	,	MZ4623
MZ4623RL	,	MZ4624	,	MZ4625	,	MZ4625RL
MZ4626	,	MZ4626RL	,	MZ4627	,	MZ4627RL
MZMA3030HT1	,	MZMA3047LT1	,	MZMA3051MT1	,	MZMA3056HT1
MZMA3056T1	,	MZMA3062MT1	,	MZMA3068MT1	,	MZMA3075MT1
MZMA3082MT1	,	MZMA3091MT1	,	MZMA3120MT1	,	MZMA3150MT1
MZMA3270HT1	,	MZMA3300MT1	,	P6KE100A	,	P6KE100ARL
P6KE10A	,	P6KE10ARL	,	P6KE110A	,	P6KE110ARL
P6KE11A	,	P6KE11ARL	,	P6KE120A	,	P6KE120ARL
P6KE12A	,	P6KE12ARL	,	P6KE130A	,	P6KE13A
P6KE13ARL	,	P6KE150A	,	P6KE150ARL	,	P6KE15A
P6KE15ARL	,	P6KE160ARL	,	P6KE16A	,	P6KE16ARL
P6KE170A	,	P6KE180A	,	P6KE180ARL	,	P6KE18A
P6KE18ARL	,	P6KE200A	,	P6KE200ARL	,	P6KE20A
P6KE20ARL	,	P6KE22ARL	,	P6KE24A	,	P6KE24ARL
P6KE27A	,	P6KE27ARL	,	P6KE30A	,	P6KE30ARL
P6KE33A	,	P6KE33ARL	,	P6KE36A	,	P6KE36ARL
P6KE39A	,	P6KE39ARL	,	P6KE43A	,	P6KE43ARL
P6KE47A	,	P6KE47ARL	,	P6KE51A	,	P6KE51ARL
P6KE56A	,	P6KE56ARL	,	P6KE6.8A	,	P6KE6.8ARL
P6KE62A	,	P6KE62ARL	,	P6KE68A	,	P6KE68ARL
P6KE7.5A	,	P6KE7.5ARL	,	P6KE75A	,	P6KE75ARL
P6KE8.2A	,	P6KE8.2ARL	,	P6KE82A	,	P6KE82ARL
P6KE9.1A	,	P6KE9.1ARL	,	P6KE91A	,	P6KE91ARL
SZ2367-1RR2	,	SZG30675-16RL	,		,	