



UPDATE CHANGE NOTIFICATION # 16750Generic Copy

Issue Date: 15-Mar-2012**TITLE:** Wafer Expansion at ON Semiconductor (Roznov, Czech Republic)**PROPOSED FIRST SHIP DATE:** 13-May-2012**AFFECTED CHANGE CATEGORY(S):** Wafer Fabrication**AFFECTED PRODUCT DIVISION:** PowerFET Business Unit**ADDITIONAL RELIABILITY DATA:**

Contact your local ON Semiconductor Sales Office or Donna Scheuch
<d.scheuch@onsemi.com>

SAMPLES: Contact your local ON Semiconductor Sales Office or Brian Goodburn
<brian.goodburn@onsemi.com>

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or Larry DeLuca
<larry.deluca@onsemi.com> or Susan Brutcher <Susan.Brutcher@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

ON Semiconductor is transferring the High Cell Density (TMOS7, HD+) MOSFET Die to their Wafer facility in Roznov, Czech Republic.

This is an updated notification to FPCN16750 which announced to Customers that ON Semiconductor is revising their change over date for Die sourcing to the Roznov Wafer Fab facility. Products will now have a Date Code of the Work Week 20, 2012 or newer.


UPDATE CHANGE NOTIFICATION #16750
List of affected General Parts:

2N7002LT1H	NTC18N06LF	NTDV2955-1G
2N7002LT3H	NTC3055L104WP	NTDV2955PT4G
2V7002LT1G	NTD18N06LT4G	NTDV3055L104-1G
2V7002LT3G	NTD20N06LT4G	NTF2955T1G
BS170G	NTD20N06T4G	NTF3055-100T1G
BS170RLRAG	NTD20P06LG	NTF3055-100T3G
BSS138LT1G	NTD20P06LT4G	NTF3055L108T1G
BSS138LT3G	NTD24N06LT4G	NTGD1100LT1G
BSS138LT3H	NTD24N06T4G	NTJD1155LT1G
BVSS138LT1G	NTD2955-1G	NTK3043NT1G
MMBF170LT1G	NTD2955G	NTP2955G
MMBFV170LT1G	NTD2955PT4G	NVF2955PT1G
MMBFV170LT3G	NTD2955T4G	NVF2955T1G
NSTJD1155LT1G	NTD2955T4H	NVF3055-100T1G
NTA4001NT1G	NTD3055-094-1G	NVF3055L108T1G
NTA4001NT1H	NTD3055-094T4G	NVF3055L108T3G
NTA7002NT1G	NTD3055-150T4G	NVR4003NT3G
NTB25P06T4G	NTD3055-150T4H	NVTA7002NT1G
NTB45N06LT4G	NTD3055L104-1G	NVTJD4001NT1G
NTB45N06T4G	NTD3055L104G	NVTJD4001NT2G
NTB5605PT4G	NTD3055L104T4G	NVTJD4158CT1G
NTB60N06T4G	NTD3055L170T4G	NVTP2955G
NTBV25P06T4G	NTDV18N06LT4G	SBVS138LT1G
NTBV5605T4G	NTDV20N06LT4G	SMBF1035LT3G
NTBV75N06T4G	NTDV20P06LT4G	STD24N06LT4G

List of affected Customer Specific Parts:

SBSS138LT1G	STD18N06LT4G	STD3055L104T4G
SMBF1060LT1G	STD20P07LT4G	