



---

**INITIAL PRODUCT/PROCESS CHANGE NOTIFICATION # 20324J**Generic Copy

---

**Issue Date:** 16-Dec-2013

**TITLE:** Test site transfer from Kanto Sanyo Semiconductors Co., Ltd to ON Semiconductor SSMP Philippines Corporation (Group 10)

**PROPOSED FIRST SHIP DATE:** 01-Sep-2014

**AFFECTED CHANGE CATEGORY(S):** Test site

**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**

Contact your local ON Semiconductor Sales Office or

<naoki.koyama@onsemi.com> <takehito.tsukui@onsemi.com> <keiji.ueda@onsemi.com>  
<shinya.okada@onsemi.com> <ikuo.saeki@onsemi.com> <takeshi2.hoshino@onsemi.com>  
<t.igarashi@onsemi.com>

**NOTIFICATION TYPE:**

Initial Product/Process Change Notification (IPCN)

First change notification sent to customers. IPCNs are issued at least 120 days prior to implementation of the change. An IPCN is advance notification about an upcoming change and contains general information regarding the change details and devices affected. It also contains the preliminary reliability qualification plan.

The completed qualification and characterization data will be included in the Final Product/Process Change Notification (FPCN).

This IPCN notification will be followed by a Final Product/Process Change Notification (FPCN) at least 90 days prior to implementation of the change.

**DESCRIPTION AND PURPOSE:**

As a part of restructuring of semiconductor production infrastructure, Hanyu plant of Kanto Sanyo Semiconductors Co., Ltd will be closed at the end of June, 2014 and have been started preparation for end of production.

In order to continue supply of applicable products under this condition, the products and the equipments will be transferred to ON Semiconductor SSMP Philippines Corporation.

**QUALIFICATION PLAN:**

Estimated Date for Qualification Completion: 30-May-2014  
Samples should be available after completion of Qualification.



**INITIAL PRODUCT/PROCESS CHANGE NOTIFICATION # 20324J**

**List of affected General Parts:**

LA1070-MPB-E  
LC823425-12G1-H  
LC823425-12G-H  
LC823430TA-2H  
LC823431TAK-2H  
LC823432TAK-2H  
LC87F5864CUTG2H  
LC89058WA-E  
LC898201TA-NH  
LC823425-12G1-LR-H

**List of affected Customer Specific Parts:**

1 1410010-MPB-E  
1410010-TRM-E  
LC24006G-15C-H  
LC823420S-12AS-H  
LC87F5864CF58F1TG-2H  
LC87F9W48A-F5CD1-H  
LC87F9W48A-F5CD3-H  
LC98500DQ-13P-H  
LC98600CT-11J-H  
LC98800DF-14A-H