



PRODUCT DISCONTINUANCE # 20120W

Issue Date: 26-Jul-2013

TITLE: Product Discontinuance Notice

LAST BUY DATE: 26-Jan-2014

LAST SHIP DATE: 26-Jul-2014

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or Theresa McCarley
<theresa.mccarley@onsemi.com>, Lea Bonita <lea.bonita@onsemi.com>.

NOTIFICATION TYPE:

Customers must notify ON Semiconductor (<quality@onsemi.com>) in writing within 30 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

DESCRIPTION AND PURPOSE:

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. ON Semiconductor continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable). For questions or concerns regarding this notification, please contact your local sales office or customer service representative.



PRODUCT DISCONTINUANCE #20120W

Additional contacts are:

Americas:

PC Wan (pc.wan@onsemi.com)
602.244.6345
USA

Europe:

Andrej Tomasik (Andrej.tomasik@onsemi.com)
+421 33790 4127
Slovakia

Japan & Asia Pacific:

Stephen Ng (Stephen.ng@onsemi.com)
(852) 2689-0209
China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

End of life buy orders must be placed before 26-Jan-2014
End of life buy orders must be shipped before 26-Jul-2014


PRODUCT DISCONTINUANCE #20120W
List of affected Parts:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
LA4525-E	NONE	NA
LA4525-V-E	NONE	NA
LA5693D-N-E	NONE	NA
LA6358NS-E	NONE	NA
LA6581U-TE-L-E	LA6581MC	ON Semi(Sanyo)
LA76931H7FB-E	NONE	NA
LB11988-E	NONE	NA
LB1205-E	LB1205M—TLM-E	ON Semi(Sanyo)
LB1205-L-E	LB1205M—TLM-E	ON Semi(Sanyo)
LB1205Z-E	NONE	NA
LB1641L-E	LV8400V-TLM-E	ON Semi(Sanyo)
LB1663-E	LB1868M	ON Semi(Sanyo)
LB1731-E	NONE	NA
LB1731-H-E	NONE	NA
LB1860-E	LB1860M	ON Semi(Sanyo)
LB1868-E	LB1868M	ON Semi(Sanyo)
LC75863E-E	NONE	NA
LC7985ND-8733-E	NONE	NA
LC87F0A08AU-EB-NH	LC87F0A08AU-EB-TLM-H	ON Semi(Sanyo)
LC898105-TBM-GB-E	LC898113-TBM-H	ON Semi(Sanyo)
LV3313PM-MPB-E	LV3313PM-TLM-E	ON Semi(Sanyo)
LV3319PM-MPB-E	LV3319PM-TLM-E	ON Semi(Sanyo)
LV51132T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51133T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51134T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51135T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51136T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51137T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV51138T-TLM-E	LC05111ZMT(under developmant)	ON Semi(Sanyo)
LV5230BG-TLM-H	NONE	NA
LV8806GQ-TE-L-H	LV8806QA-MH	ON Semi(Sanyo)
LA5693D-E	NONE	NA
LA5693MC-AH	LA5693MD-AH	ON Semi(Sanyo)
LC74735NW-9817-E	NONE	NA
LA6585M-TLM-H	LA6585MC	ON Semi(Sanyo)
LA6597FM-TLM-H	LA6597FMC	ON Semi(Sanyo)
LA76931H7N59R4-E	NONE	NA
LB11861-N-TLM-H	LB11861JA	ON Semi(Sanyo)
LB11861M-TLM-H	LB11861MC	ON Semi(Sanyo)
LB1862M-TLM-H	LB1862MC	ON Semi(Sanyo)
LB1962M-TLM-H	LB1962MC	ON Semi(Sanyo)
LC24006G-15F-AE	NONE	NA
LC651102N-4M86-TLM-E	LC872H08A	ON Semi(Sanyo)


PRODUCT DISCONTINUANCE #20120W

Device to be Discontinued	Recommended Replacement	Supplier
LC651104N-4N05-TLM-E	LC872H08A	ON Semi(Sanyo)
LC651104N-4N06-TLM-E	LC872H08A	ON Semi(Sanyo)
LC6528C-4826-E	LC87BK04A	ON Semi(Sanyo)
LC66404A-4K28-E	LC875G07B	ON Semi(Sanyo)
LC70310KBG-UAQ-TLM-H	LC70310KBG-TLM-H	ON Semi(Sanyo)
LC79450KB-X2T-CN	LC79450KB-UCZ	ON Semi(Sanyo)
LC867108A-5S12-E	LC877648C	ON Semi(Sanyo)
LC872D09B-59M5	NONE	NA
LC87F10C8A-F59N0-E	LC87F10C8A-SQFP64	ON Semi(Sanyo)
LC87F10C8A-F5AF9-E	LC87F10C8A-SQFP64	ON Semi(Sanyo)
LC87F10C8A-F5BD1-E	LC87F10C8A-SQFP64	ON Semi(Sanyo)
LV5046FN-TLM-E	NONE	NA
LA9900U-A-E	NONE	NA
LA9900U-B-E	NONE	NA
LA9900U-C-E	NONE	NA
LA9901U-A-E	NONE	NA
LA9901U-B-E	NONE	NA
LA9901U-C-E	NONE	NA
LA9901U-N2-E	NONE	NA
LA9902U-E	NONE	NA
LC5864H-1D37-E	LC877648C	ON Semi(Sanyo)
LC5864H-1N29-E	LC877648C	ON Semi(Sanyo)
LC587008-1P96-E	LC877648C	ON Semi(Sanyo)
LC5872-1A11-E	LC877648C	ON Semi(Sanyo)
LC587404A-1P10-E	LC877917A	ON Semi(Sanyo)
LC651102N-4M87-TLM-E	LC872H08A	ON Semi(Sanyo)
LC651104N-4M85-TLM-E	LC872H08A	ON Semi(Sanyo)
LC865508B-52S0-E	LC875G07B	ON Semi(Sanyo)
LC871W32A-5BE8-E	NONE	NA
LC87F1A32A-F58Z7-E	LC87F1HC(A	ON Semi(Sanyo)
LC87F1A32A-F5AR0-E	LC87F1A32AUWA-2H	ON Semi(Sanyo)
LC87F1A32A-F5BP4-E	LC87F1A32AUWA-2H	ON Semi(Sanyo)
LC87F1J2A-F5BR7-H	LC87F1J2AUWA-2H	ON Semi(Sanyo)
LC87F1M16A-F5BM3-H	LC87F1M16AUWA-2H	ON Semi(Sanyo)
LC87F4164A-F59N1-E	NONE	NA
LC87F4164A-F59S8-E	NONE	NA
LC87F4164A-F5BG5-E	NONE	NA
LC87F5G32A-F59V3-E	LC87F5G32AUWA-2H	ON Semi(Sanyo)
LC87F6AC8AF5BT4EJ-2H	NONE	NA
LC87F6AC8A-F5CA0-H	LC87F6AC8ALU-EJ-H	ON Semi(Sanyo)
LC88F0348A2300-TLM-E	NONE	NA