



Title of Change:	Update to PB21821X - List of previously announced SOT5X3 products that will not be affected by the improved cross bar tape change at ON Semiconductor Leshan, China factory.
Effective date:	27 October 2017
Contact information:	Contact your local ON Semiconductor Sales Office or <Coleen.Long@onsemi.com>
Type of notification:	ON Semiconductor will consider this change accepted.
Change category:	<input type="checkbox"/> Wafer Fab Change <input type="checkbox"/> Assembly Change <input type="checkbox"/> Test Change <input checked="" type="checkbox"/> Other <u>Cross Bar of Carrier Tape Change</u>

Change Sub-Category(s):		<input type="checkbox"/> Datasheet/Product Doc change
<input type="checkbox"/> Manufacturing Site Change/Addition	<input type="checkbox"/> Material Change	<input checked="" type="checkbox"/> Shipping/Packaging/Marking
<input type="checkbox"/> Manufacturing Process Change	<input type="checkbox"/> Product specific change	<input type="checkbox"/> Other:

Sites Affected:			
<input type="checkbox"/> All site(s)	<input type="checkbox"/> not applicable	<input checked="" type="checkbox"/> ON Semiconductor site(s): ON Leshan, China	<input type="checkbox"/> External Foundry/Subcon site(s)

Description and Purpose:

This Update Notice is to inform the customers of the list of SOT5X3 products that will not be affected by the change identified in the previously released PB21821X.

PB21821X was previously released to announce the improved SOT5X3 cross bar of carrier tape to eliminate potential risk of unit rotate in tape.

List of SOT5X3 Parts that were previously announced and which will not be Affected by the change:

STZD5110NT1G	NSBC124XPDXV6T1G	NSBA143EDXV6T1G	SNUF2042XV6T1G	NL17SZ14XV5T2G
NTZD5110NT1G	NSBC124XDXV6T1G	NSBA124XDXV6T1G	NUF2230XV6T1G	NL17SZ126XV5T2G
NSTB1005DXV5T1G	NSBC124EPDXV6T1G	NSBA124EDXV6T1G	NUF2042XV6T1G	NL17SZ08XV5T2GH
NSTB1002DXV5T1G	NSBC124EDXV6T1G	NSBA123EDXV6T1G	NZQA6V8XV5T1G	NL17SZ07XV5T2G
NST3946DXV6T1G	NSBC123JPDXV6T1G	NSBA115EDXV6T1G	NZQA6V8AXV5T3G	NL17SZ06XV5T2G
NST3906DXV6T1G	NSBC123JDXV6T1G	NSBA114YDXV6T1G	NZQA6V8AXV5T2G	NL17SZ02XV5T2G
NST3904DXV6T1G	NSBC123EPDXV6T1G	NSBA114TDXV6T1G	NZQA6V8AXV5T1G	NL17SZ00XV5T2G
NST30010MXV6T1G	NSBC123EDXV6T1G	NSBA114EDXV6T1G	NZQA6V2XV5T1G	NL17SV32XV5T2G
NSS12100XV6T1G	NSBC115EDXV6T1G	NSBA113EDXV6T1G	NZQA5V6XV5T1G	NL17SV16XV5T2G
NSR0320XV6T1G	NSBC114YPDXV6T1G	EMX1DXV6T1G	NZQA5V6AXV5T1G	NL17SV08XV5T2G
NSDEMP11XV6T1G	NSBC114YDXV6T1G	EMT1DXV6T1G	NUP5120X6T2G	NL17SV04XV5T2G
NSBC144WDXV6T1G	NSBC114TPDXV6T1G	EMD4DXV6T1G	NUP5120X6T1G	NL17SV02XV5T2G
NSBC144EPDXV6T1G	NSBC114TDXV6T1G	EMC4DXV5T1G	NUP4114UPXV6T1G	NL17SV00XV5T2G
NSBC144EDXV6T1G	NSBC114EDXV6T1G	EMC3DXV5T1G	NUP4102XV6T1G	STZD3155CT1G
NSBC143ZPDXV6T1G	NSBC113EPDXV6T1G	EMC2DXV5T1G	NUP4060AXV6T1G	NTZS3151PT1G
NSBC143ZDXV6T1G	NSBC113EDXV6T1G	BC858CDXV6T1G	NUP2114UPXV5T1G	NTZD3155CT2G
NSBC143TPDXV6T1G	NSBA144WDXV6T1G	BC847CDXV6T1H	NL17SZU04XV5T2G	NTZD3155CT1G
NSBC143TDXV6T1G	NSBA144EDXV6T1G	BC847CDXV6T1G	NL17SZ32XV5T2G	NTZD3154NT1G
NSBC143EPDXV6T1G	NSBA143ZDXV6T1G	BC847BPDV6T1G	NL17SZ17XV5T2GH	NTZD3152PT1G
NSBC143EDXV6T1G	NSBA143TDXV6T1G	BAS16DXV6T1G	NL17SZ16XV5T2G	