



<b>Title of Change:</b>	Update to PD23933ZB : 1Q2021 Product Discontinuance Notice - Batch 4 (Standard) - Reactivation of FDMC8588
<b>Last Time Buy Date:</b>	NA
<b>Last Ship Date:</b>	NA
<b>Contact information:</b>	Contact your local ON Semiconductor Sales Office or <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a>
<b>Type of notification:</b>	Customers must notify ON Semiconductor (< <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

### Description and Purpose:

ON Semiconductor wishes to inform customer of this update to PD23933ZB, announcing the reactivation of FDMC8588 in the previously discontinued parts listed in this notice which shall continue production.

This update notice is issued upon customer's request.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

#### Americas:

Tom Siegel ([tom.siegel@onsemi.com](mailto:tom.siegel@onsemi.com))

☎ +1 765 868 5022

USA

#### Japan:

Isao Usuki ([isao.usuki@onsemi.com](mailto:isao.usuki@onsemi.com))

☎ +81 3 6880 1771

Japan

#### Europe:

Andrej Tomasik ([andrej.tomasik@onsemi.com](mailto:andrej.tomasik@onsemi.com))

☎ +421 33790 2229

Slovakia

#### Asia Pacific:

Stephen Ng ([stephen.ng@onsemi.com](mailto:stephen.ng@onsemi.com))

☎ +852 2689 0209

China

### List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Part Number	Replacement part	Supplier
FDMC8588	NA	N/A