



PRODUCT BULLETIN # 20696

Generic Copy

Issue Date: 09-Jan-2015

TITLE: Change in inner box design.

PROPOSED FIRST SHIP DATE: 09-Jan-2015

AFFECTED CHANGE CATEGORY(S): Packing material

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor sales office or

<Hidemichi.Nomura@onsemi.com><Hiroshi2.Kobayashi@onsemi.com>

<Daisuke.Murakami@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:


Change in Inner box design as part of the integration into the packing material of ON Semi spec.

Basic Dimensions Comparison

	Current				Proposed
	BOX(TE-2412)		BOX(SMP)		ON Semi Pizza Box
	Measurement	Difference	Measurement	Difference	Measurement
Length	832 mm	25 mm	863 mm	56 mm	807 mm
Width	467 mm	107 mm	491 mm	83 mm	574 mm
Height	35 mm	13 mm	47 mm	1 mm	48 mm
Actual					



PRODUCT BULLETIN #20696



List of affected General Parts:

LA1776M-MPB-E	LC72135MA-AE	LC75827WS-E
LA1780MA-A-MPB-E	LC72137MA-AE	LC75827W-SH-E
LA1781MD-B-MPB-E	LC72146MA-AH	LC75829PEH-H
LA1781ML-MPB-E	LC72191JMA-AH	LC75832E-E
LA1781M-MPB-E	LC72717PW-H	LC75832EH-E
LA1787M-MPB-E	LC72722PM-TLM-E	LC75832ES-E
LA1787NM-TLM-E	LC74761M-9006-E	LC75832WS-E
LA1844MC-AH	LC74763M-9602-E	LC75852EHS-E
LA5744MP-E	LC75410ES-E	LC75852W-E
LA5771MP-E	LC75410WS-E	LC75852W-TLM-E
LA5774MC-BE	LC75412EH-E	LC75853NE-E
LA5774MP-E	LC75412WH-D-E	LC78615E-01US-H
LA5779MP-E	LC75412WS-UF-E	LC85405JE-E
LA6242H-E	LC75725E-E	LC877917A-QIP-E
LA6548NH-E	LC75821ED-E	LC87F2G08AUMJ-ZH
LA6584M-TLM-E	LC75821E-E	LC87F5JC8AU-QIP-E
LA6584M-TLM-H	LC75821EHS-E	LC87F5M64AU-QIP-E
LB11961RM-TLM3-E	LC75822ED-E	LC87F5M64AVU-QIP-E
LB11961RM-TLM3-H	LC75822EHS-E	LC87F5R96BU-QIP-E
LB1923M-TLM-E	LC75822EHS-T-E	LV25350PW-TLM-E
LC709006A-E	LC75822WD-E	LV3320M-TLM-E
LC709006V-E	LC75827E-E	LV5236V-MPB-H
LC72121MA-AH	LC75827ES-E	LV59001MC-AH
LC72131KMA-AE	LC75827W-E	


PRODUCT BULLETIN #20696
List of affected Customer Specific Parts:

0339-671-TLM-E	LC72191JMA-UC-AH	LC875J48C-5CA3-E
051-4016-00-MPB-E	LC7234-8490-E	LC875J64C-58J2-E
B11961FML-NMB-TLM3-E	LC72714W-TLM-E	LC877917A-5BY2-E
LA4930M-TLM-E	LC72715PW-SH-UD-H	LC87F2G08AV5BM4MJ-AH
LA6584M-ND-TLM-E	LC72715PW-TLM-H	LC87F5JC8A-F5BK2-E
LB11961FML-ND-TLM3-H	LC72715PW-UP-H	LC87F5JC8A-F5BP6-E
LB11967V-NMB-TLM3-E	LC75827W-UCN-TBM-E	LC87F5M64A-F5BB2-E
LB1663M-DELTA-TLM-H	LC75829PWS-T-UNS-H	LV25400W-FJT-MPB-E
LB1868M-NMB-TLM3-E	LC75853NE-Q-E	LV25450PW-F-MPB-E
LC5739-1N65-E	LC75857EH-SH-UC-E	LV8900M-H-TRM-E
LC651432N-4M03-E	LC786810E-6C01-H	LC865508A-5J91-TRM-E
LC703200AW-8C04-H		