



PCN# : P645AAB
Issue Date : Apr. 12, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.


This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :

1. Existing Figure 1, On-Region Characteristics (page 3)
2. Existing Figure 3, On-Resistance Variation vs. Drain Current and Gate Voltage (page 3)



Description of Change (To) :

1. Updated Figure 1, On-Region Characteristics (page 3)
2. Updated Figure 3, On-Resistance Variation vs. Drain Current and Gate Voltage (page 3)




Figure 1. On-Region Characteristics




Figure 3. On-Resistance Variation vs. Drain Current and Gate Voltage

Reason for Change:

This is a Datasheet change only.

Figures 1 and 3 were updated and corrected based on correct test data.

Affected Product(s):

FQB34P10TM_F085	FQB34P10TM_F085P	FQB34P10TM_TF085
-----------------	------------------	------------------