

PCN#: P636AAB

Issue Date : Mar. 14, 2016

## **Information Only Notification**

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

## **Implementation of change:**

Description of Change (From):

Drain-Source Diode Characteristics, QRR (Reverse Recovery Charge) Typ/Max: 31/45 nC (page 2)

Description of Change (To):

Drain-Source Diode Characteristics, QRR (Reverse Recovery Charge) Typ/Max: 21/35 nC (page 2)

Reason for Change:

Datasheet change only.

The Reverse Recovery Charge (Qrr) specification is being corrected back to its original limits. A test result was misinterpreted and upon test verification, the error is being corrected.



## Affected Product(s):

FDS9958_F085   FDS9958_SB82210   FDS9958_TSB82210	FDS9958_F085	FDS9958_SB82210	FDS9958_TSB82210	
---	--------------	-----------------	------------------	--