



Product Discontinuance

Document #:PD24446X2

Issue Date:14 Jan 2022

| | |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Title of Change: | Update to PD24446X - Product Discontinuance for Tower Jazz (Fab) products with extended EOL dates |
| Last Time Buy Date: | 31 Jan 2022 |
| Last Ship Date: | 31 Jan 2023 |
| Contact information: | Contact your local onsemi Sales Office or PCN.Support@onsemi.com |
| Type of notification: | Customers must notify onsemi (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life. |

Description and Purpose:

onsemi is publishing this document to notify the extended EOL dates for product listed in this notice.

onsemi wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)
☎ +1 765 868 5022
USA

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)
☎ +421 33790 2229
Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com)
☎ +81 3 6880 1771
Japan

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)
☎ +852 2689 0209
China

UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, onsemi ALLOWS CUSTOMERS TO PLACE FINAL LIFETIME PURCHASE ORDERS UNTIL JAN. 31, 2022. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS.

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

| Device to be Discontinued | Replacement part | Supplier |
|---------------------------|------------------|----------|
| NDS356AP | #NONE | #NA |
| FDC6323L | #NONE | #NA |
| FDC6325L | #NONE | #NA |

| | | |
|--------------|----------|--------|
| FDC2512 | #NONE | #NA |
| FDD5614P | #NONE | #NA |
| FDD5670 | #NONE | #NA |
| FDMC5614P | #NONE | #NA |
| MTD3055V | #NONE | #NA |
| BSS123W | #NONE | #NA |
| BSS84-G | #NONE | #NA |
| FDC3535 | #NONE | #NA |
| FDD3510H | #NONE | #NA |
| FDD3680 | #NONE | #NA |
| FDD5612 | #NONE | #NA |
| FDD5690 | #NONE | #NA |
| FDS5690 | #NONE | #NA |
| FDS8935 | #NONE | #NA |
| MTD3055VL | #NONE | #NA |
| NDB6060L | #NONE | #NA |
| NDP7060 | #NONE | #NA |
| FDC2512-P | #NONE | #NA |
| BSS123-F169 | #NONE | #NA |
| FDMC5614P-B8 | #NONE | #NA |
| FDG6320C | #NONE | #NA |
| FDV301N-F169 | #NONE | #NA |
| BSS138-F169 | BSS138 | onsemi |
| FDD6685-G | #NONE | #NA |
| FDG6332C-PG | #NONE | #NA |
| FDS4465-G | #NONE | #NA |
| FDV303N-F169 | #NONE | #NA |
| 2N7002-F169 | 2N7002 | onsemi |
| 9G85-BSS138 | BSS138 | onsemi |
| FDC638P-P | #NONE | #NA |
| FDC6333C-G | #NONE | #NA |
| FDMA1027PT | #NONE | #NA |
| FDS4465-PG | #NONE | #NA |
| FDY100PZ-G | #NONE | #NA |
| BSS84-F169 | BSS84 | onsemi |
| FDC5612-G | FDC5661N | onsemi |
| FDC5614P-G | FDC5614P | onsemi |

| | | |
|----------------------|--------------------------------|--------|
| FDMC5614P-L701 | NTTF55116PL (as higher spec) | onsemi |
| FDN5618P-B8 | NTF2955 | onsemi |
| FDN5630-B8 | NTR5198NL | onsemi |
| FDN5630-G | NTR5198NL | onsemi |
| FDS5690-NBBM009A | FDS3572 (as higher spec) | onsemi |
| G785-BSS123 | BSS123 | onsemi |
| NDS0605-F169 | NDS0605 | onsemi |
| NDS0610-PG | NDS0610 | onsemi |
| NDS7002A-F169 | NDS7002A | onsemi |
| PCFA3612D | #NONE | #NA |
| DMYTADNFAZ08TNS-TJAA | #NONE | #NA |
| FDT3612-SN00151 | FDT3612 | onsemi |