



PRODUCT DISCONTINUANCE # 20120G

Issue Date: 26-Jul-2013

TITLE: Product Discontinuance Notice

LAST BUY DATE: 26-Jan-2014

LAST SHIP DATE: 26-Jul-2014

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or Theresa McCarley
<theresa.mccarley@onsemi.com>, Lea Bonita <lea.bonita@onsemi.com>.

NOTIFICATION TYPE:

Customers must notify ON Semiconductor (<quality@onsemi.com>) in writing within 30 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

DESCRIPTION AND PURPOSE:

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. ON Semiconductor continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable). For questions or concerns regarding this notification, please contact your local sales office or customer service representative.



PRODUCT DISCONTINUANCE #20120G

Additional contacts are:

Americas:

PC Wan (pc.wan@onsemi.com)
602.244.6345
USA

Europe:

Andrej Tomasik (Andrej.tomasik@onsemi.com)
+421 33790 4127
Slovakia

Japan & Asia Pacific:

Stephen Ng (Stephen.ng@onsemi.com)
(852) 2689-0209
China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

End of life buy orders must be placed before 26-Jan-2014
End of life buy orders must be shipped before 26-Jul-2014


PRODUCT DISCONTINUANCE #20120G
List of affected Parts:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
LA6585M-TLM-H	LA6585MC	ON Semi(Sanyo)
LA76931J7N5AC1-E	NONE	NA
LB11861M-TLM-H	LB11861MC	ON Semi(Sanyo)
LB1862M-TLM-H	LB1862MC	ON Semi(Sanyo)
LB1962M-TLM-H	LB1962MC	ON Semi(Sanyo)
LB8070-E	NONE	NA
LC24085BT-XJ5-E	NONE	NA
LC573202A-1P25	LC877917A	ON Semi(Sanyo)
LC651104N-4N05-TLM-E	LC872H08A	ON Semi(Sanyo)
LC6527N-4G42-E	LC87BK04A	ON Semi(Sanyo)
LC6528C-4826-E	LC87BK04A	ON Semi(Sanyo)
LC6528N-4F50-E	LC87BK04A	ON Semi(Sanyo)
LC66404A-4L88-E	LC875G07B	ON Semi(Sanyo)
LC70310KBG-UAQ-TLM-H	LC70310KBG-TLM-H	ON Semi(Sanyo)
LC70310KBG-UNY-TLM-H	LC70310KBG-TLM-H	ON Semi(Sanyo)
LC70701LG-USR-H	NONE	NA
LC749403BG-E	NONE	NA
LC786922E-UM-E	NONE	NA
LC865508A-5K74-E	LC875G07B	ON Semi(Sanyo)
LC865508B-5V88-E	LC875G07B	ON Semi(Sanyo)
LC867108A-5S12-E	LC877648C	ON Semi(Sanyo)
LC87F10C8A-F59N0-E	LC87F10C8A-SQFP64	ON Semi(Sanyo)
LC87F10C8A-F5AF9-E	LC87F10C8A-SQFP64	ON Semi(Sanyo)
LC89057W-VF4AD-E	LC89057W-VF4A-E	ON Semi(Sanyo)
LC5851N-1A39-E	LC877917A	ON Semi(Sanyo)
LC5851N-1E89-E	LC877917A	ON Semi(Sanyo)
LC587008-1P62-E	LC877648C	ON Semi(Sanyo)
LC587204A-1L05-E	LC877917A	ON Semi(Sanyo)
LC5872-1A11-E	LC877648C	ON Semi(Sanyo)
LC5872-1C10-E	LC877648C	ON Semi(Sanyo)
LC5873-1E26-E	LC877648C	ON Semi(Sanyo)
LC5873-1F64-E	LC877648C	ON Semi(Sanyo)
LC5873-1G76-E	LC877648C	ON Semi(Sanyo)
LC587406A-1N87-E	LC877917A	ON Semi(Sanyo)
LC587406A-1N93-E	LC877917A	ON Semi(Sanyo)
LC587406A-1P53-E	LC877917A	ON Semi(Sanyo)
LC587406A-1P72-E	LC877917A	ON Semi(Sanyo)
LC651102N-4M87-TLM-E	LC872H08A	ON Semi(Sanyo)
LC651301A-4N13-TLM-E	LC87BK04A	ON Semi(Sanyo)
LC723782N-9D02-E	NONE	NA
LC723782N-9D23-E	NONE	NA
LC723782N-9D42-E	NONE	NA
LC723782N-9D52-E	NONE	NA


PRODUCT DISCONTINUANCE #20120G

Device to be Discontinued	Recommended Replacement	Supplier
LC723784-9D28-E	NONE	NA
LC786960E-17UM-H	NONE	NA
LC786960PE-14SM-LR-H	NONE	NA
LC863332C-55J6-E	NONE	NA
LC863532C-55J2-E	NONE	NA
LC863532C-55K9-E	NONE	NA
LC863532C-55L1-E	NONE	NA
LC863532C-57K6-E	NONE	NA
LC863532C-58E2-E	NONE	NA
LC865508A-5S16	LC875G07B	ON Semi(Sanyo)
LC865508B-52S0-E	LC875G07B	ON Semi(Sanyo)
LC865520B-53H1-E	LC875G24A	ON Semi(Sanyo)
LC875816A-56F1-E	NONE	NA
LC875CB2A-59S3-E	LC87F5WC8A	ON Semi(Sanyo)
LC875D48C-5AE1-E	LC87F5WC8A	ON Semi(Sanyo)
LC877812A-59K0-E	LC877917A	ON Semi(Sanyo)
LC877816A-58K7-E	LC877917A	ON Semi(Sanyo)
LC877816A-58S2-E	LC877917A	ON Semi(Sanyo)
LC877B32A-57Z6-E	LC87F7NC8A	ON Semi(Sanyo)
LC877B32A-5AB3-E	LC87F7NC8A	ON Semi(Sanyo)
LC877B48A-58D9-E	LC87F7NC8A	ON Semi(Sanyo)
LC877B64A-55W1-E	LC87F7NC8A	ON Semi(Sanyo)
LC877B64A-55W2-E	LC87F7NC8A	ON Semi(Sanyo)
LC877B96A-59T5-E	LC87F7NC8A	ON Semi(Sanyo)
LC877C24C-56V1-E	LC87F76C8A	ON Semi(Sanyo)
LC877C24C-57D0-E	LC87F76C8A	ON Semi(Sanyo)
LC8783J2PA-59P1-E	NONE	NA
LC8783J3PA-58L4-E	NONE	NA
LC8783M4PA-59P0-E	NONE	NA
LC8783P6PA-59K5-E	NONE	NA
LC8783P6PA-59R9-E	NONE	NA
LC87F05J2A-F59B7-E	NONE	NA
LC87F1G64A-F58F8-E	NONE	NA
LC87F1HC8A-F59L1-E	LC87F1HC8AUWA-2H	ON Semi(Sanyo)
LC87F1HC8A-F59M3-E	LC87F1HC8AUWA-2H	ON Semi(Sanyo)
LC87F1HC8A-F5AJ4-E	LC87F1HC8AUWA-2H	ON Semi(Sanyo)
LC87F6AC8AF5BY5EJ-2H	LC87F6AC8ALU-EJ-H	ON Semi(Sanyo)
LC87F6AC8A-F5CA0-H	LC87F6AC8ALU-EJ-H	ON Semi(Sanyo)
LC87F7CC8A-F56A1-E	LC87F76C8A	ON Semi(Sanyo)
LC88F0348A2307-TLM-E	NONE	NA