



PCN# : P5BHAAB
Issue Date : Jun. 29, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :

WLCSP - Maine Bump Fab, Penang, Malaysia Mfg Site

Description of Change (To) :

WLCSP - Amkor T5 Bump Fab, Amkor T3 Assy Site

Reason for Change:

Maine Bump Fab, Penang, Malaysia Mfg Site Shutdown

This is a custom PCN for Merlot only - the actual PCN document is attached in the Google Docs, Notes & Attachments section as a Word Document. The PCN system was not used to distribute the PCN. Noel Sy is responsible for informing Merlot of this PCN. Improvement in cost competency to allow Fairchild to sustain long term commercial support to Apple.



Affected Product(s):

FPF1039UCX		
------------	--	--