



---

**UPDATE CHANGE NOTIFICATION # 16789A**Generic Copy

---

**Issue Date:** 25-May-2012

**TITLE:** Update Notification to Previous Issued FPCN16789 (Announcement of alternative product delivery associated with SSTH - Sanyo Semiconductor Thailand flood damage) for part LB1948M-TE-L-E only.

**PROPOSED FIRST SHIP DATE:** 25-May-2012 (or earlier with customer approval)

**AFFECTED CHANGE CATEGORY(S):** Correct New Part Number Typo for part LB1948M-TE-L-E

**ADDITIONAL RELIABILITY DATA:** Not Applicable (see original FPCN16789)

**SAMPLES:** Contact your local ON Semiconductor Sales Office

**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:** Contact your local ON Semiconductor Sales Office.

For affected devices below in Group A thru Group H (see original FPCN16789), contact

<[Tetsuya.Ishizuka@onsemi.com](mailto:Tetsuya.Ishizuka@onsemi.com)>

For affected devices in Group I and Group J (see original FPCN16789), contact

<[Toshikazu.Hirai@onsemi.com](mailto:Toshikazu.Hirai@onsemi.com)>

**SAMPLES:** Contact your local ON Semiconductor Sales Office or <[Akira.Yoneyama@onsemi.com](mailto:Akira.Yoneyama@onsemi.com)>

**ADDITIONAL RELIABILITY DATA:** Contact your local ON Semiconductor Sales Office.

For affected devices below in Group A thru Group H (see original FPCN16789), contact

<[Shoji.Suematsu@onsemi.com](mailto:Shoji.Suematsu@onsemi.com)>

For affected devices in Group I and Group J (see original FPCN16789), contact

<[Osamu.Ishihara@onsemi.com](mailto:Osamu.Ishihara@onsemi.com)>

**DESCRIPTION AND PURPOSE:**

The purpose of this Update Notification is to just correct a New Part Number Typo.

Wrong/Incorrect: LB1948MC-BH (identified on the original FPCN16789 in Group H)

Correct: LB1948MC-AH

All other information and data remains the same as originally issued in FPCN16789.

**List of affected General Parts:**

Current Part Number	NEW Part Number
LB1948M-TE-L-E	LB1948MC-AH