

INITIAL PRODUCT/PROCESS CHANGE NOTIFICATION #20102

Generic Copy

Issue Date: 12-Jun-2013

<u>TITLE:</u> MFP10SK products transfer from Taihei Electronics Co., Ltd to Sanyo Semiconductor Manufacturing Philippines Corporation (SSMP)

PROPOSED FIRST SHIP DATE: 12-Oct-2013

AFFECTED CHANGE CATEGORY(S): MFP10SK assembly site, facilities, materials

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or <Tetsuro Maruyama@onsemi.com> <Naoki Koyama@onsemi.com>

SAMPLES: Contact your local ON Semiconductor Sales Office

<u>ADDITIONAL RELIABILITY DATA</u>: Available Contact your local ON Semiconductor Sales Office or <Satoru Fuinuma@onsemi.com>

NOTIFICATION TYPE:

Initial Product/Process Change Notification (IPCN)

First change notification sent to customers. IPCNs are issued at least 120 days prior to implementation of the change. An IPCN is advance notification about an upcoming change and contains general information regarding the change details and devices affected. It also contains the preliminary reliability qualification plan.

The completed qualification and characterization data will be included in the Final Product/Process Change Notification (FPCN).

This IPCN notification will be followed by a Final Product/Process Change Notification (FPCN) at least 90 days prior to implementation of the change.

DESCRIPTION AND PURPOSE:

Products transfer from Taihei Electronics Co., Ltd to SSMP (Philippines)

Taihei Electronics Co., Ltd, sub-con in Japan will close their outsource business at the end of Jun 2013 (MFP10SK). We need to transfer MFP10SK products to other sites.

Equipment and materials will be changed by transferring site and have proven sufficient in other packages in SSMP.

There is no change to the package external dimensions and shipping form.

Issue Date: 12-Jun-2013 Rev. 06-Jan-2010 Page 1 of 2



INITIAL PRODUCT/PROCESS CHANGE NOTIFICATION #20102

QUALIFICATION PLAN:

Estimated Date for Qualification Completion: Aug/23/2013 Samples should be available after completion of Qualification.

List of affected General Parts:

LA6583MC-AH

LA6588MC-AH

LA6588MC-BH

LB11861MC-AH

LB1846MC-AH

LB1862MC-AH

LB1948MC-AH

LB1948MC-BH

LB1948MC-ZH

LC87F2608AUMM-AH

List of affected Customer Specific Parts:

LA6588M-TE-L-H

LB11861M-TLM-H

LB1862M-TLM-H

LC87F2608A59W3MM-AH

LC87F2608A5BW9MM-AH

Issue Date: 12-Jun-2013 Rev. 06-Jan-2010 Page 2 of 2