



PCN# : P63AAAB
Issue Date : Mar. 28, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :

1. Figure 2 (page 2), Figure 13 (page 20) , Figure 25 and Figure 26 (page 40): Block diagrams did not include TVS detail
2. Table 28, Note 39 (page 35), included "or Test Modes" in first sentence.
3. No TVS information was included

Description of Change (To) :

1. Figure 2, Figure 13, Figure 25 and Figure 26 : Block diagram updated to add details for TVS diodes
2. Table 28, Note 39 , removed unnecessary words "or Test Modes" from this sentence.
3. "Appropriate TVS selection" section added with Table 43 is added on page 42

Reason for Change:

This is a datasheet change only.

The datasheet is being updated to add more details and guidelines to customers in regards to selecting appropriate TVS Diodes to use with the FSA9688C.



Affected Product(s):

FSA9688CUCX		
-------------	--	--