



---

**PRODUCT BULLETIN # 16958**Generic Copy

---

**Issue Date:** 30-Jan-2013**TITLE:** Announcement of Removal of "SANYO" Logo from LSI Products**PROPOSED FIRST SHIP DATE:** The change will be made starting May 1st, 2013**AFFECTED CHANGE CATEGORY(S):** Shipping - all Sanyo parts with SANYO Logo**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**Contact your local ON Semiconductor sales office/sales person or  
[Gunma.Yuzayukyuhinshitsush@onsemi.com](mailto:Gunma.Yuzayukyuhinshitsush@onsemi.com)**SAMPLES:** Contact your local ON Semiconductor Sales Office/sales person or  
[Hiroshi2.Kobayashi@onsemi.com](mailto:Hiroshi2.Kobayashi@onsemi.com)**NOTIFICATION TYPE:**

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact &lt;quality@onsemi.com&gt;.

**DESCRIPTION AND PURPOSE:**

Sanyo logo will be replaced by ON Semiconductor logo. For temporary period devices will be without logo until ON logo will be released for these devices

1. All products printed with the SANYO logo. (Please refer the attached products list.)

[Before the change sample]

With SANYO Logo

[After the change sample]

Without SANYO Logo



2. All product shipping trays imprinted with the SANYO logo. (Not limited with the attached products list.)

3. All product shipping magazines printed with the SANYO logo. (Not limited with the attached products list.)

**PRODUCT BULLETIN #16958****List of affected General Parts:**

1. Products list printed with the SANYO logo on the device package.

LA4440J-K-E  
LB1240-E  
LB1256-E  
LB1257-E  
LB1290-E  
LB1740-E  
LC35256FM-70U-E  
LC35256FM-70UHG-E  
LC35256FM-70UHGTLM-E  
LC35256FM-70U-TLM-E  
LC35256FT-70UHGTLM-E  
LC35256FT-70UHS-E  
LC35256FT70UHSTLM-E  
LC35256FT-70U-TLM-E  
LC3564CM-70U-E  
LC3564CM-70UHS-TLM-E  
LC3564CM-70U-TLM-E  
LC35V256ET-70W-TLM-E  
LC35W256ET10WHSTLM-E  
LC749880T-E  
LC75833E-E  
LC75833EHS-E  
LC75883EHS-E  
LC7886M-TRM-E  
LC79401D-E  
LC7985ND-8733-E  
LC821033-E  
LC82210-LA2-E  
LC82561-PB5C-E  
LC89052TA-E  
LE28F4001CTS12-MPB-E



**PRODUCT BULLETIN #16958**

**List of affected Customer Specific Parts:**

LC21006B-RF7-E  
LC21006C-Y11-E  
LC21041B-LE2-E  
LC22004B-PG5-TRM-E  
LC22017CT-RB2-E  
LC22060C-TA2-E  
LC27047C-RJ0-E  
LC27273B-TD9-E  
LC5873-1G76-E  
LC66404A-4L88-E  
LC72323-9250-E  
LC72323-9427-E  
LC7234-8490-E  
LC72366-9448-E  
LE28F4001CTS-12G10-E  
LE28F4001CTS-12H10-E  
LV8900M-H-MPB-E  
LV8900M-H-TRM-E