

Product Bulletin

Document #:PB25983Z1 Issue Date:04 Apr 2024

Title of Change:	Update to PB25983Z - Introduce new orderable part numbers Assemble and Test at onsemi Seremban, Malaysia using 12-inch wafer from Global Foundries East Fishkill, US.	
Effective date:	04 Apr 2024	
Contact information:	Contact your local onsemi Sales Office or <u>Hoang.Nguyen@onsemi.com</u>	
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.	
Change Category:	Wafer Fab Change	
Change Sub-Category(s):	Material Change	
Sites Affected:		
onsemi Sites		External Foundry/Subcon Sites
None		Global Foundries East Fishkill, New York, United States

Description and Purpose:

This notification is an update to PB25983Z to correct Fab information of the OPNs listed in the notification and to provide additional clarification on this change.

onsemi is introducing new orderable part numbers for parts assembled at onsemi Seremban, Malaysia using 12-inch wafers from Global Foundries East Fishkill, US. This flow was originally released under FPCN22966 series using the existing OPN but with -01 suffix in the IPN field of product labels. With the release of new OPNs for the parts assembled at onsemi Seremban, Malaysia using 12-inch wafers from Global Foundries East Fishkill, US the OPN and IPN will be the same.

Original OPNs Fab: Aizu 8-inch/ EFK 12-inch Assembly: Seremban Test: Seremban	New OPNs Fab: EFK 12-inch Assembly: Seremban Test: Seremban Per P825983Z
NVMFS4C302NWFT1G	NVMFS4C302NWFET1G
NVMFS5C423NLWFAFT1G	NVMFS5C423NLWFET1G
NVMFS5C450NLWFAFT1G	NVMFS5C450NLWFET1G
NVMFS5C450NWFAFT1G	NVMFS5C450NWFET1G
NVMFS5C450NWFAFT3G	NVMFS5C450NWFET3G
NVMFS5C456NLWFAFT1G	NVMFS5C456NLWFET1G
NVMFS5C456NLWFAFT3G	NVMFS5C456NLWFET3G
NVMFS5C460NLWFAFT1G	NVMFS5C460NLWFET1G
NVMFS5C460NLWFAFT3G	NVMFS5C460NLWFET3G
NVMFS5C468NLWFAFT3G	NVMFS5C468NLWFET3G
NVMFS5C646NLWFAFT1G	NVMFS5C646NLWFET1G
NVTFS5C680NLWFTAG	NVTFS5C680NLWFETAG
NVMFS5C404NLWFAFT3G	NVMFS5C404NLWFET3G
NVMFS5C404NWFAFT1G	NVMFS5C404NWFET1G
NVMFS5C410NLWFAFT1G	NVMFS5C410NLWFET1G
NVMFS5C410NLWFAFT3G	NVMFS5C410NLWFET3G
NVMFS5C410NWFAFT1G	NVMFS5C410NWFET1G
NVMFS5C426NWFAFT1G	NVMFS5C426NWFET1G
NVMFS5C430NLWFAFT3G	NVMFS5C430NLWFET1G
NVMFS5C430NWFAFT1G	NVMFS5C430NWFET1G
NVMFS5C442NLWFAFT1G	NVMFS5C442NLWFET1G

TEM001797 Rev. D Page 1 of 2



Product Bulletin

Document #:PB25983Z1 Issue Date:04 Apr 2024

	NVMFS5C442NWFAFT1G	NVMFS5C442NWFET1G	
NVMFS5C442NWFAFT3G		NVMFS5C442NWFET3G	

Original OPNs Fab: Gresham 8-inch/ EFK 12-inch Assembly: Seremban Test: Seremban	New OPNs Fab: EFK 12-inch Assembly: Seremban Test: Seremban Per PB25983Z	
NVMFS4C03NWFT1G	NVMFS4C303NWFET1G	
NVMFS4C05NWFT1G	NVMFS4C05NWFET1G	

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

NVMFS5C442NWFAFT3G	NVMFS5C442NWFAFT1G	NVMFS5C442NLWFAFT1G
NVMFS5C430NWFAFT1G	NVMFS5C430NLWFAFT3G	NVMFS5C426NWFAFT1G
NVMFS5C410NWFAFT1G	NVMFS5C410NLWFAFT3G	NVMFS5C410NLWFAFT1G
NVMFS5C404NWFAFT1G	NVMFS5C404NLWFAFT3G	NVTFS5C680NLWFTAG
NVMFS5C646NLWFAFT1G	NVMFS5C468NLWFAFT3G	NVMFS5C460NLWFAFT3G
NVMFS5C460NLWFAFT1G	NVMFS5C456NLWFAFT1G	NVMFS5C450NWFAFT3G
NVMFS5C450NWFAFT1G	NVMFS4C03NWFHT1G	NVMFS4C05NWFHT1G
NVMFS4C302NWFHT1G	NVMFS5C423NLWFHT1G	NVMFS5C450NLWFHT1G
NVMFS5C450NWFHT1G	NVMFS5C450NWFHT3G	NVMFS5C456NLWFHT1G
NVMFS5C456NLWFHT3G	NVMFS5C460NLWFHT1G	NVMFS5C460NLWFHT3G
NVMFS5C468NLWFHT3G	NVMFS5C646NLWFHT1G	NVTFS5C680NLWFHTAG
NVMFS5C404NLWFHT3G	NVMFS5C404NWFHT1G	NVMFS5C410NLWFHT1G
NVMFS5C410NLWFHT3G	NVMFS5C410NWFHT1G	NVMFS5C426NWFHT1G
NVMFS5C430NLWFHT1G	NVMFS5C430NWFHT1G	NVMFS5C442NLWFHT1G
NVMFS5C442NWFHT1G	NVMFS5C442NWFHT3G	NVMFS4C302NWFT1G
NVMFS5C423NLWFAFT1G	NVMFS5C450NLWFAFT1G	NVMFS5C456NLWFAFT3G

TEM001797 Rev. D Page 2 of 2