## onsemi

## Product Bulletin Document #:PB25221X Issue Date:23 Jan 2023

Title of Change:	NCP3286 family datasheet typo fixes					
Effective date:	23 Jan 2023					
Contact information:	Contact your local onsemi Sales Office or Wayne.Cheng@onsemi.com					
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.					
Change Category:	Information Only					
Change Sub-Category(s):	Information Only					
Sites Affected:						
onsemi Sites		External Foundry/Subcon Sites				
None		None				

## Description and Purpose:

This Product Bulletin is to announce the change of NCP3286 / NCP3296 datasheet as below NCP3286 P.44 – correcting Vout(V) typographical error in Table 71 NCP3296 P.16 – correcting Rpin(K $\Omega$ ) typographical error in Table 2

	Change from					Change to						
NCP3286 P.44 Table 71						_						
	V <sub>OUT</sub> (V	Data	(h)	V <sub>OUT</sub> (V)	Data (h)			V <sub>OUT</sub> (V)	Data (h)	)	V <sub>OUT</sub> (V)	Data (h)
	0.8	0000	C	1.8	01CD			0.8	00CD		1.8	01CD
	1.0	0100	)	15	034D			1.0	0100		3.	034D
	1.2	0133	3	18	0500	1		1.2	0133		J <b>P</b> 5.	0500
NCP3296 P.16 Table 2				_								
	182	1.20	2.20	5.00	15			182	1.20	2.20	5.00	15
	open	1.25	2.30	5.50	20			<b>22</b> ′	1.25	2.30	5.50	20

## List of Affected Standard Parts:

**Note**: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

NCP3296MNTXG	NCP3286MNTXG	
--------------	--------------	--