



## Product Discontinuance

Document #:PD23900Z8

Issue Date:11 Jan 2022

<b>Title of Change:</b>	Updated to PD23900Z - Reactivation of previously discontinued parts.
<b>Last Time Buy Date:</b>	NA
<b>Last Ship Date:</b>	NA
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:Sungdae.Shin@onsemi.com">Sungdae.Shin@onsemi.com</a>
<b>Type of notification:</b>	Customers must notify onsemi (< <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

### Description and Purpose:

This is to formally inform customers of the reactivation of devices listed in this Notification, that were previously discontinued in PD23900Z. Parts shall be considered active.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

#### Americas:

Tom Siegel ([tom.siegel@onsemi.com](mailto:tom.siegel@onsemi.com))

☎ +1 765 868 5022

USA

#### Japan:

Isao Usuki ([isao.usuki@onsemi.com](mailto:isao.usuki@onsemi.com))

☎ +81 3 6880 1771

Japan

#### Europe:

Andrej Tomasik ([andrej.tomasik@onsemi.com](mailto:andrej.tomasik@onsemi.com))

☎ +421 33790 2229

Slovakia

#### Asia Pacific:

Stephen Ng ([stephen.ng@onsemi.com](mailto:stephen.ng@onsemi.com))

☎ +852 2689 0209

China

### List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

Part Number	Replacement part	Supplier
NFAL5012L5BT	#NONE	#NA
NFAL5012L5B	#NONE	#NA
NFAL3512L5BT	#NONE	#NA
NFAL3512L5B	#NONE	#NA
NFAL2512L5B	#NONE	#NA
NFAL1512L5B	#NONE	#NA