



UPDATE CHANGE NOTIFICATION # 16200Generic Copy

Issue Date: 24-Feb-2015

TITLE: Update of Phase 2 Copper Wire for VHVIC Products in SOIC and TSSOP packages in Carmona, Philippines

PROPOSED FIRST SHIP DATE: 28-Sept-2015

AFFECTED CHANGE CATEGORY(S): Assembly Process

ADDITIONAL RELIABILITY DATA: Available (see original FPCN 16200)

SAMPLES: Contact your local ON Semiconductor Sales Office

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor Sales Office or <Scott.Brow@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

In order to provide Cu wire samples of all devices requested after the release of FPCN16200 and allow our customers the appropriate 90 days for qualification and verification, ON Semiconductor would like to notify all customers that the proposed first shipment date of product with Cu wires will be changed from 20-Apr-2015 to 28-Sept-2015.


UPDATE CHANGE NOTIFICATION #16200
List of affected General Parts:

NCL30000DR2G	NCP1244AD100R2G	NCP1288BD65R2G	NCP1652DR2G
NCL30001DR2G	NCP1244BD065R2G	NCP1336ADR2G	NCP1652DWR2G
NCL30002DR2G	NCP1244BD100R2G	NCP1336BDR2G	NCP1654BD133R2G
NCL30051DR2G	NCP1246AD065R2G	NCP1379DR2G	NCP1654BD200R2G
NCP1218AD65R2G	NCP1246AD100R2G	NCP1380ADR2G	NCP1654BD65R2G
NCP1219AD100R2G	NCP1246ALD065R2G	NCP1380BDR2G	NCP1910A100DWR2G
NCP1219AD65R2G	NCP1246ALD100R2G	NCP1380CDR2G	NCP1910A65DWR2G
NCP1219BD100R2G	NCP1246BD065R2G	NCP1380DDR2G	NCP1910B100DWR2G
NCP1219BD65R2G	NCP1246BD100R2G	NCP1392BDR2G	NCP1910B65DWR2G
NCP1234AD100R2G	NCP1246BLD065R2G	NCP1392DDR2G	NCP1927DR2G
NCP1234AD65R2G	NCP1246BLD100R2G	NCP1393BDR2G	NCP4304ADR2G
NCP1234BD100R2G	NCP1247AD065R2G	NCP1396ADR2G	NCP4304BDR2G
NCP1234BD65R2G	NCP1247AD100R2G	NCP1396BDR2G	NCP4810DR2G
NCP1236AD100R2G	NCP1247BD065R2G	NCP1397ADR2G	NCP5104DR2G
NCP1236AD65R2G	NCP1247BD100R2G	NCP1397BDR2G	NCP5106ADR2G
NCP1236BD100R2G	NCP1247CD065R2G	NCP1398BDR2G	NCP5106BDR2G
NCP1236BD65R2G	NCP1247CD100R2G	NCP1398CDR2G	NCP5109ADR2G
NCP1236DD65R2G	NCP1247DD065R2G	NCP1562ADR2G	NCP5109BDR2G
NCP1237AD65R2G	NCP1247DD100R2G	NCP1562BDR2G	NCP5111DR2G
NCP1237BD65R2G	NCP1252ADR2G	NCP1607BDR2G	NCP5304DR2G
NCP1238AD65R2G	NCP1252BDR2G	NCP1608BDR2G	SCY99102BDR2G
NCP1238BD65R2G	NCP1252CDR2G	NCP1631DR2G	SCY991608BDR2G
NCP1240AD100R2G	NCP1271D100R2G	NCP1652ADR2G	NCP1271D65R2G
NCP1244AD065R2G			


UPDATE CHANGE NOTIFICATION #16200
List of affected Customer Specific Parts:

SCY08957ADR2G	SCY99079BDR2G	SCY99089DR2G	SCY99123BDR2G
SCY08957BDR2G	SCY99079CD1R2G	SCY99092DR2G	SCY99124DR2G
SCY08957DDR2G	SCY99079CDR2G	SCY99096DR2G	SCY99126AD065R2G
SCY08957EDR2G	SCY99079FD1R2G	SCY99098DR2G	SCY99126AD100R2G
SCY99068DR2G	SCY99079FDR2G	SCY99103ADR2G	SCY99126BD065R2G
SCY99073A1DR2G	SCY99079FPDR2G	SCY99103BDR2G	SCY99126BD100R2G
SCY99073ADR2G	SCY99082BDR2G	SCY99105ADR2G	SCY99146AD065R2G
SCY99073B1DR2G	SCY99085ADR2G	SCY99105BDR2G	SCY99146AD100R2G
SCY99073BDR2G	SCY99087ADR2G	SCY99105FDR2G	SCY99146BD065R2G
SCY99073CDR2G	SCY99087BDR2G	SCY99106BDR2G	SCY99146BD100R2G
SCY99076ADR2G	SCY99088ADR2G	SCY99106CDR2G	SCY991562CDR2G
SCY99076AR2G	SCY99088BDR2G	SCY99109AD65R2G	SCY99157CDR2G
SCY99076BDR2G	SCY99088CADR2G	SCY99111ADR2G	SCY99157DDR2G
SCY99076BR2G	SCY99088CDR2G	SCY99111BDR2G	SCY991606BEDR2G
SCY99079AD1R2G	SCY99088DADR2G	SCY99117DR2G	SCY99168DR2G
SCY99079ADR2G	SCY99088DDR2G	SCY99121DR2G	SCY991900DWR2G
SCY99079BD1R2G	SCY99088HDR2G		