



PRODUCT BULLETIN #16958A

Generic Copy

Issue Date: 15-Aug-2013

TITLE: Announcement of Removal of "SANYO" Logo from LSI Products

PROPOSED FIRST SHIP DATE: The change will be made starting Nov 1st, 2013

AFFECTED CHANGE CATEGORY(S): Shipping - all Sanyo parts with SANYO Logo

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact your local ON Semiconductor sales office or (Katsuhiko.lizuka@onsemi.com)

NOTIFICATION TYPE:

ON Semiconductor considers this change approved unless specific conditions of acceptance are provided in writing. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

The "SANYO" logo on SANYO Semiconductor products will be removed.

[Before the change sample]
With SANYO Logo

[After the change sample]
Without SANYO Logo



**PRODUCT BULLETIN #16958A****List of affected General Parts:**

LA1888NML-E
LA1888NM-MPB-E
LA1888NM-S-MPB-E
LA9420M-MPB-E
LB1720-E
LC7574FE-E
LC75833ED-E
LC75873NW-E
LC75873NWHS-SH-E
LC75883E-E
LC75883W-E
LC75883WHS-E
LC78625E-E
LC89051VHS-TLM-E
LE25FV451T-MPB-E
LC12018-EV
LC12018-TBM-E
LC7234-9253-E
LC749400W-E
LC78620E-E
LC78621ED-E

List of affected Customer Specific Parts:

LC24031B-XE8-E
LC5733-1F14-E
LC5851N-1E89-E
LC5864H-1D37-E
LC5864H-1N29-E
LC5872-1A11-E
LC5872-1M24-E
LC5873-1E26-E
LC5873-1F64-E
LC66404A-4K28-E
LC72323-9299-E
LC72323-9380-E
LC72323-9444-E
LC72336-9446-E
LC7574FE-USV-E
LC75873NE-QR-TBM-E
LE28F4001CTS-12L01-E