

<b>Title of Change:</b>	Update to PD24446X - Reactivation of previously discontinued part
<b>Last Time Buy Date:</b>	NA
<b>Last Ship Date:</b>	NA
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a>
<b>Type of notification:</b>	Customers must notify onsemi (< <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

## Description and Purpose:

onsemi wishes to inform customers of the reactivation of device below that was previously discontinued in PD24446X. The part shall be considered active.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

### Americas:

Tom Siegel (tom.siegel@onsemi.com)  
 ☎ +1 765 868 5022  
 USA

### Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)  
 ☎ +421 33790 2229  
 Slovakia

### Japan:

Isao Usuki (isao.usuki@onsemi.com)  
 ☎ +81 3 6880 1771  
 Japan

### Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)  
 ☎ +852 2689 0209  
 China

## List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Part Number	Replacement part	Supplier
NDS9407	#NONE	#NA
FDS4559	#NONE	#NA
FDN5618P	#NONE	#NA
FDN5630	#NONE	#NA
FDC3512	#NONE	#NA
FDC5612	#NONE	#NA
FDS3580	#NONE	#NA
FDC6306P	#NONE	#NA
FDS9933A	#NONE	#NA
FDS6975	#NONE	#NA
FDS6875	#NONE	#NA
FDD6630A	#NONE	#NA

SI4532DY	#NONE	#NA
NDT451AN	#NONE	#NA
FDN336P	#NONE	#NA
FDS6890A	#NONE	#NA
FDN342P	#NONE	#NA
FDT439N	#NONE	#NA
FDS9431A	#NONE	#NA
FDS6986AS	#NONE	#NA
FDS4435A	#NONE	#NA
FDT457N	#NONE	#NA