



PCN# : P64LAAB
Issue Date : May. 03, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :

Fabrication Site: Fairchild Salt Lake City, UT and Assembly Site: Fairchild Penang

Description of Change (To) :

Fabrication Site: 8-inch wafer manufacturing at Fairchild Mountain Top, PA and Fairchild Bucheon, Korea, and multiple external sites as listed in the table and Assembly Site: Multiple sites (internal and external as listed in the table)

Reason for Change:

This is a custom PCN for Merlot only - the actual PCN document is attached in the Google Docs, Notes & Attachments section as a Word Document. The PCN system was not used to distribute the PCN. Noel Sy is responsible for informing Merlot of this PCN.

Affected Product(s):

FAN53501UCX	FDC2512	FDC637BNZ
FDMA530PZ	FDMC8200	FDME1034CZT
FDMS0346	FDMS0349	FDMS0355S
FDMS3616S	FMS6353EUCX	