



PCN# : P64IAAB
Issue Date : May. 04, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.


Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :


Marking layout : "XXX".

"XXX" is last 3 digits of assembly lot number.



Description of Change (To) :

Marking layout : "ZKK".
"Z" is plant code , "KK" is trace code.



Reason for Change:
Assembly lot traceability improvement.

Affected Product(s):

FBA42060	FBA42060_T	FCA22012A
FCBB20CH60SF	FCBS0550	FNA21012A
FNA22512A	FNA23060	FNA23512A
FNA23512A_T	FNA25060	FNA25060S
FNA27560	FNA40560	FNA40860
FNA40860B2	FNA41060	FNA41060B2
FNA41060B2_T	FNA41560	FNA41560B2
FNA41560B2_F057	FNA41560B2_F151	FNA41560B2_T
FNA41560B4	FNB33060T	FNB40560
FNB40560B2	FNB40560_SN00282	FNB40560_T
FNB41060	FNB41060B2	FNB41060_F151
FNB41060_T	FNB41560	FNB41560B2
FNB41560_F151	FNB41560_T	FNB43060T2
FNC42060F	FNC42060F2	FNC42060F2_T
FNCS1560L	FNCS3060L	FNE40560
FNE41060	FNE41060_T	FNH44004P
FNH46004P	FPA22012A	FPA23012A
FPAB20BH60B	FPAB20BH60B_T	FPAB30BH60
FPAB30BH60B	FPAB30BH60B_T	FPAM30LH60
FPAM30LH60S	FPAM30LH60_T	FPAM50LH60
FPAM50LH60G	FPAM50LH60S	FPCS1560L
FPCS3060L	FPDB30PH60	FPDB40PH60B
FPDB40PH60B_SN00372	FPDB40PH60B_T	FPDB50PH60
FPDB50PH60_F166	FPDB60PH60B	FPDB60PH60B_SN00373
FPDB60PH60B_T	FPDL10BH60	FPDL10BH60L
FPDL15BH60	FSAM10SH60A	FSAM15SH60A
FSAM20SH60A	FSAM20SM60A	FSAM20SM60A_T
FSAM30SH60A	FSAM30SM60A	FSAM30SM60A_T
FSAM30SM60SL	FSAM50SM60A	FSAM50SM60A_T
FSAM50SM60G	FSAM50SM60G_T	FSAM75SM60A
FSAM75SM60SL	FSB32560	FSB43004A
FSB44104A	FSB50250	FSB50250A
FSB50250AB	FSB50250AS	FSB50250AT
FSB50250AT_T	FSB50250UD	FSB50250US
FSB50250UTD	FSB50260SF	FSB50325A
FSB50325AP	FSB50325AS	FSB50325AT
FSB50325AT_SN00263	FSB50325T	FSB50350ASF
FSB50350ATF	FSB50450	FSB50450A
FSB50450AS	FSB50450AS_SN00272	FSB50450AT
FSB50450S	FSB50450TB2	FSB50450UD

Affected Product(s):

FSB50450US	FSB50550A	FSB50550AB
FSB50550AD	FSB50550ADL	FSB50550AS
FSB50550ASE	FSB50550AT	FSB50550T
FSB50550TB2	FSB50550US	FSB50550UTD
FSB50660SF	FSB50660SFS	FSB50660SFT
FSB50760SF	FSB50760SFS	FSB50760SFT
FSB50760SFT_T	FSB50825A	FSB50825AB
FSB50825AS	FSB50825TB	FSB50825TB2
FSB50825US	FSB52006S	FSBB10CH120D
FSBB10CH120DF	FSBB15CH60	FSBB15CH60C
FSBB15CH60D	FSBB15CH60F	FSBB15CH60F_F166
FSBB20CH60	FSBB20CH60C	FSBB20CH60CL
FSBB20CH60CT	FSBB20CH60CTSL	FSBB20CH60C_F139
FSBB20CH60C_SN00327	FSBB20CH60C_SN00374	FSBB20CH60C_T
FSBB20CH60D	FSBB20CH60F	FSBB20CH60F_F166
FSBB20CH60L	FSBB20CH60SL	FSBB20CH60_T
FSBB25CH60DS	FSBB30CH60	FSBB30CH60C
FSBB30CH60CM	FSBB30CH60CS	FSBB30CH60CT
FSBB30CH60C_SN00326	FSBB30CH60C_SN00375	FSBB30CH60C_T
FSBB30CH60D	FSBB30CH60DF	FSBB30CH60F
FSBB30CH60FM	FSBB30CH60F_F166	FSBF10CH60B
FSBF10CH60BT	FSBF10CH60BTL	FSBF10CH60BTSL
FSBF10CH60BT_T	FSBF15CH60BT	FSBF15CH60BTH
FSBF15CH60BT_T	FSBF15CH60CT	FSBF15CH60CT_T
FSBF5CH60B	FSBF5CH60BS	FSBF5CH60BS_T
FSBS10CH60	FSBS10CH60L	FSBS10CH60L_T
FSBS10CH60SL	FSBS10CH60T	FSBS10CH60_T
FSBS10SM60I	FSBS15CH60	FSBS15CH60F
FSBS15CH60F_F166	FSBS15CH60L	FSBS15CH60L_T
FSBS15CH60_T	FSBS3CH60	FSBS5CH60
FSBS8CH60T	FSSN50CH60	FSSN50CH60M
FSSP50CH60S	FSSP50CH60S_T	FTBV1P5SH50U
FTBV1SH25U	FTBV1SH25X	FTBV1SH50U
FTBV1SH50X	FTBVP5SH50U	FTBVP5SH50X
NBC9610	NBC9611	NBC9612
NBC9613	NBC9614	NBC9615
NBC9616	NBC9619	NBC9620
NBC9624		