



## Product Discontinuance

Document #:PD24582ZA2

Issue Date:08 Aug 2022

<b>Title of Change:</b>	Update to PD24582ZA - Reactivation of SZNSP8814LMTWTAG
<b>Last Time Buy Date:</b>	NA
<b>Last Ship Date:</b>	NA
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:Maya.AbuBakar@onsemi.com">Maya.AbuBakar@onsemi.com</a>
<b>Type of notification:</b>	Customers must notify onsemi (< <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

### Description and Purpose:

onsemi wishes to inform our customers of our intent to reactivate of the device listed below, which were previously discontinued in PD24582ZA.

The part shall be considered active.

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

#### Americas:

Tom Siegel ([tom.siegel@onsemi.com](mailto:tom.siegel@onsemi.com))

☎ +1 765 868 5022

USA

#### Europe:

Andrej Tomasik ([andrej.tomasik@onsemi.com](mailto:andrej.tomasik@onsemi.com))

☎ +421 33790 2229

Slovakia

#### Japan:

Isao Usuki ([isao.usuki@onsemi.com](mailto:isao.usuki@onsemi.com))

☎ +81 3 6880 1771

Japan

#### Asia Pacific:

Stephen Ng ([stephen.ng@onsemi.com](mailto:stephen.ng@onsemi.com))

☎ +852 2689 0209

China

### List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Part Number	Replacement part	Supplier
SZNSP8814LMTWTAG	#NONE	#NA