



PRODUCT DISCONTINUANCE # 20624Generic Copy

Issue Date: 28-Aug-2014**TITLE:** 2SC2814-5-TB-E Discontinuance**LAST BUY DATE:** Not Applicable**LAST SHIP DATE:** Not Applicable**FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:**

Contact your local ON Semiconductor Sales Office or Theresa McCarley
<theresa.mccarley@onsemi.com>, Lea Bonita <lea.bonita@onsemi.com>.

DESCRIPTION AND PURPOSE:

Production of the 2SC2814 was discontinued in June, 2011. The OPN# 2SC2814-5-TB-E was also discontinued accordingly. The EOL announcement of this product was made via the former SANYO Semiconductor's website. However this website was closed and consolidated to the ON Semiconductor's website. Therefore, there is no EOL information of this product in the current website because the product had already been discontinued at the migration of the website.

While we regret any inconvenience this announce may cause, we would like to supply your future product requirements with our extensive product lines.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

PC Wan (pc.wan@onsemi.com)
602.244.6345
USA

Europe:

Andrej Tomasik (Andrej.tomasik@onsemi.com)
+421 33790 4127
Slovakia

Japan & Asia Pacific:

Stephen Ng (Stephen.ng@onsemi.com)
(852) 2689-0209
China

NOTE:

End of life buy orders must be placed before	Not Applicable
End of life buy orders must be shipped before	Not Applicable

**PRODUCT DISCONTINUANCE # 20624****List of affected General Parts:**

Device to be Discontinued	Recommended Replacement	Supplier
2SC2814-5-TB-E	15GN01CA-TB-E 15GN03CA-TB-E 55GN01CA-TB-E	ON Semiconductor