

<b>Title of Change:</b>	Update to PD24134X - Reactivation of NSP8814MUTAG and NSP8818MUTAG parts.
<b>Last Time Buy Date:</b>	NA
<b>Last Ship Date:</b>	NA
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:norhayati.othman@onsemi.com">norhayati.othman@onsemi.com</a>
<b>Type of notification:</b>	Customers must notify onsemi (< <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

## Description and Purpose:

onsemi wishes to inform customers the reactivation of the devices listed below, which were previously discontinued in PD24134X.

The parts shall be considered active.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel ([tom.siegel@onsemi.com](mailto:tom.siegel@onsemi.com))

☎ +1 765 868 5022

USA

Japan:

Isao Usuki ([isao.usuki@onsemi.com](mailto:isao.usuki@onsemi.com))

☎ +81 3 6880 1771

Japan

Europe:

Andrej Tomasik ([andrej.tomasik@onsemi.com](mailto:andrej.tomasik@onsemi.com))

☎ +421 33790 2229

Slovakia

Asia Pacific:

Stephen Ng ([stephen.ng@onsemi.com](mailto:stephen.ng@onsemi.com))

☎ +852 2689 0209

China

## List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [\*\*PCN Customized Portal\*\*](#).

Part Number	Replacement part	Supplier
NSP8818MUTAG	N/A	N/A
NSP8814MUTAG	N/A	N/A