

DESIGN/PROCESS CHANGE NOTIFICATION

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification. Alternatively, you may send an email request for information to PCNSupport@fairchildsemi.com.


Implementation of change:

Expected First Shipment Date for Changed Product : Sep. 02, 2013

Expected First Date Code of Changed Product :1336




Description of Change (From) :
Laser Marking layout based on Monthly code.

Datecode(Work week)			
2nd digit (Year)		3rd digit (Month)	
2010	A	P01	A
2011	B	P02	B
2012	C	P03	C
2013	D	P04	D
2014	E	P05	E
2015	F	P06	F
2016	G	P07	G
2017	H	P08	H
2018	J	P09	I
2019	K	P10	J
2020	A	P11	K
2021	B	P12	L



Description of Change (To) :
Laser Marking layout based on Weekly code.

YEAR CODE		WORK WEEK CODE					
		Workweek	Single Character Translation	Workweek	Single Character Translation	Workweek	Single Character Translation
2010	A						
2011	B	01	----	1		37	----
2012	C	02	----	2		38	----
2013	D	03	----	3		39	----
2014	E	04	----	4		40	----
2015	F	05	----	5		41	----
2016	G	06	----	6		42	----
2017	H	07	----	7		43	----
2018	J	08	----	8		44	----
2019	K	09	----	9		45	----
2020	A	10	----	0		46	----
2021	B	11	----	A		47	----
		12	----	B		48	----
		13	----	C		49	----
		14	----	D		50	----
		15	----	F		51	----
		16	----	G		52	----
		17	----	H		53	----
		18	----	J			
				19	----		
				20	----		
				21	----		
				22	----		
				23	----		
				24	----		
				25	----		
				26	----		
				27	----		
				28	----		
				29	----		
				30	----		
				31	----		
				32	----		
				33	----		
				34	----		
				35	----		
				36	----		



Reason for Change:

To improve lot traceability and narrow down for risk range

Affected Product(s):

FDY100PZ	FDY100PZ_G	
----------	------------	--