



UPDATE CHANGE NOTIFICATION # 20696

Generic Copy

Issue Date: 14-Apr-2015

TITLE: Update Notice to PB20696 - Change in inner box design

PROPOSED FIRST SHIP DATE: 21-Apr-2015

AFFECTED CHANGE CATEGORY(S): Packing material

SAMPLES: Contact your local ON Semiconductor Sales Office

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

<Rowena.Naigar@onsemi.com><Hiroshi2.Kobayashi@onsemi.com>
<Dennis.Balignasay@onsemi.com>

NOTIFICATION TYPE:

ON Semiconductor will consider this change approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice. To do so, contact <quality@onsemi.com>.

DESCRIPTION AND PURPOSE:

This update is issued to remove devices which were not affected by the change in inner box design on the original PB20696.

List of affected General Parts:

LA1776M-MPB-E	LC72131KMA-AE	LC75822ED-E	LC75832WS-E
LA1780MA-A-MPB-E	LC72135MA-AE	LC75822EHS-E	LC75852EHS-E
LA1781MD-B-MPB-E	LC72717PW-H	LC75822EHS-T-E	LC75852W-E
LA1781ML-MPB-E	LC74761M-9006-E	LC75822WD-E	LC75853NE-E
LA1781M-MPB-E	LC74763M-9602-E	LC75827E-E	LC78615E-01US-H
LA1787M-MPB-E	LC75410ES-E	LC75827ES-E	LC85405JE-E
LA5744MP-E	LC75410WS-E	LC75827W-E	LC877917A-QIP-E
LA5771MP-E	LC75412EH-E	LC75827WS-E	LC87F2G08AUMJ-ZH
LA5774MP-E	LC75412WH-D-E	LC75827W-SH-E	LC87F5JC8AU-QIP-E
LA5779MP-E	LC75412WS-UF-E	LC75829PEH-H	LC87F5M64AU-QIP-E
LA6242H-E	LC75725E-E	LC75832E-E	LC87F5M64AVU-QIP-E
LA6548NH-E	LC75821ED-E	LC75832EH-E	LC87F5R96BU-QIP-E
LC709006A-E	LC75821E-E	LC75832ES-E	LV5236V-MPB-H
LC709006V-E	LC75821EHS-E		

**UPDATE CHANGE NOTIFICATION #20696****List of affected Customer Specific Parts:**

051-4016-00-MPB-E	LC72715PW-SH-UD-H	LC786810E-6C01-H	LC87F5JC8A-F5BP6-E
LC5739-1N65-E	LC72715PW-UP-H	LC875J48C-5CA3-E	LC87F5M64A-F5BB2-E
LC651432N-4M03-E	LC75829PWS-T-UNS-H	LC875J64C-58J2-E	LV25400W-FJT-MPB-E
LC703200AW-8C04-H	LC75853NE-Q-E	LC877917A-5BY2-E	LV25450PW-F-MPB-E
LC7234-8490-E	LC75857EH-SH-UC-E	LC87F5JC8A-F5BK2-E	