

Product Bulletin

Document #:PB23127X Issue Date:12 Feb 2020

Title of Change:	AR0238 Datasheet Update	
Effective date:	12 Feb 2020	
Contact information:	Contact your local ON Semiconductor Sales Office or Sonya.Yip@onsemi.com	
Type of notification:	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.	
Change Category:	Documentation Change	
Change Sub-Category(s):	Datasheet/Product Doc change	

Sites Affected:

ON Semiconductor Sites	External Foundry/Subcon Sites	
None	None	

Description and Purpose:

Updated case outlines (package drawings) in the AR0238CS datasheet with the latest revisions.


1. Updated CASE 776AQ

Old Revision D

AR0238

PLOCASE T/RAQ ISSUE D MITCH CASE T/RAQ ISSU

New Revision F



TEM001796 Rev. B Page 1 of 2



Product Bulletin


Document #:PB23127X Issue Date:12 Feb 2020


2. Updated CASE 776AS

Old Revision A

New Revision D

AR0238





rins information is generic. Prease repair device data sheet for actual part markin Pb-Free indicator, "G" or microdot "s", ma or may not be present. Some products ma not follow the Generic Marking.

List of Affected Standard Parts:

BOTTOM VIEW

+ atSCAE

RECOMMENDED MOUNTING FOOTPRINT

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

AR0238CSSC12SHRA0-DP1	AR0238CSSC12SHRA0-DR	AR0238CSSC12SHRA0-DP
AR0238CSSC12SPRA0-DR	AR0238CSSC12SPRA0-DR1	AR0238CSSC12SUD20
AR0238IRSH12SUD20		

TEM001796 Rev. B Page 2 of 2