

ON Semiconductor

5005 East McDowell Road Phoenix, AZ 85008

http://onsemi.com

PRODUCT ALERT 31 MAY2007

ON Semiconductor wishes to notify all customers who have purchased the following parts of a potential application issue with this product.

ON Semiconductor Part Types:

NCP1606ADR2G NCP1606BDR2G NCP1606APG NCP1606BPG

Affected Manufacturing Lot Numbers:

All products sampled or purchased prior to June 2007.

Summary of evaluations and findings:

When Vcc collapses slowly, the last output drive pulse can stay on for several microseconds longer than desired, which can potentially saturate the inductor and cause failure.

Modifications are being implemented on the product to improve robustness without affecting the parametric performance of the device. All products shipped after June 20th will be of the improved version.

For assistance, please contact;

Asia Pac/Japan: Kelvin Tsiang, Product Marketing Patrick Wang, Senior Applications Eng

Phone: 852-2-6890-234 886-2-23761-170

Mail: <u>kelvin.tsiang@onsemi.com</u> <u>patrick.wang@onsemi.com</u>

Europe: Marc Barboni, Product Marketing Christophe Basso, Senior Applications Eng

Phone: 33 5 34 61 11 49 33 5 34 61 11 54

Email: marc.barboni@onsemi.com christophe.basso@onsemi.com

USA: Christophe Warin, Marketing Mgr Jon Kraft, Senior Applications Eng

Phone:602-244-6154480-477-1080Email:christophe.warin@onsemi.comJon.Kraft@onsemi.com

Important note: You must determine what actions to take to notify anyone who has procured affected product directly or indirectly from you.