

Information Only Notification

This is to inform you that a change is being made to the following products.


This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :

Current Lock reel supplied by GPI Malaysia has no poka yoke hole and is prone to mis-insertion and mis-reeling during Tape and Reel process.



Description of Change (To) :

New Lock reel from UPAK Philippines has 3 poka yoke holes that will prevent mis-insertion and mis-reeling during Tape and Reel process.



Reason for Change:

To prevent mis-reeling of devices during tape and reel operation and shorten the delivery lead time by 4-5 weeks, by ordering the parts from UPAK Philippines.

Affected Product(s):

74AC00MTCX	74AC00SJX	74AC04MTCX
74AC04SJX	74AC08MTCX	74AC08SJX
74AC138MTCX	74AC138SCX	74AC138SCX_SF501499
74AC138SJX	74AC139MTCX	74AC139SCX
74AC14MTCX	74AC14SJX	74AC240SJX
74AC244MTCX	74AC244SJX	74AC245MTCX
74AC32MTCX	74AC32SJX	74AC540MTCX
74AC540SJX	74AC541MTCX	74AC541SJX
74AC86MTCX	74ACT00MTCX	74ACT00SJX
74ACT04MTCX	74ACT08MTCX	74ACT138SCX
74ACT138SJX	74ACT139MTCX	74ACT139SCX
74ACT14MTCX	74ACT240MTCX	74ACT240SJX
74ACT244MTCX	74ACT244SJX	74ACT245MTCX
74ACT245SJX	74ACT32MTCX	74ACT541MTCX
74ALVC00MTCX	74ALVC08MTCX	74ALVC162244TX
74ALVC16244MTDX	74ALVC16245MTDX	74LCX00MTCX
74LCX00SJX	74LCX02MTCX	74LCX02SJX
74LCX04MTCX	74LCX04SJX	74LCX06MTCX
74LCX07MTCX	74LCX07SJX	74LCX08MTCX
74LCX08SJX	74LCX112MTCX	74LCX112MX
74LCX11MTCX	74LCX125MTC	74LCX125MTCX
74LCX125SJX	74LCX126MTC	74LCX126MTCX
74LCX138MTCX	74LCX138MX	74LCX14MTCX
74LCX14SJX	74LCX157MTCX	74LCX157MX
74LCX162244MTDX	74LCX162373MTDX	74LCX162374MTDX
74LCX16240MTDX	74LCX16244MTDX	74LCX16245MTDX
74LCX16373MTDX	74LCX16374MTDX	74LCX16500MTDX
74LCX16501MTDX	74LCX16543MTDX	74LCX16646MTDX
74LCX2244MTCX	74LCX240MTCX	74LCX240SJX
74LCX244MTCX	74LCX244SJX	74LCX245MTCX
74LCX245SJX	74LCX257MTCX	74LCX257MX
74LCX32MTCX	74LCX32SJX	74LCX373MTCX
74LCX373SJX	74LCX374MTCX	74LCX374SJX
74LCX38MTCX	74LCX38SJX	74LCX540MTCX
74LCX541MTCX	74LCX541SJX	74LCX543MTCX
74LCX573MTCX	74LCX573SJX	74LCX574MTCX
74LCX574SJX	74LCX652MTCX	74LCX74MTCX
74LCX760MTCX	74LCX821MTCX	74LCX86MTCX
74LCXH162244MTX	74LCXH16244MTDX	74LCXH16245MTDX
74LCXH245MTCX	74LCXP16245MTDX	74LCXR162245MTX

Affected Product(s):

74LCXR2245MTCX	74LCXZ16244MTDX	74LCXZ16245MTDX
74LVT162244MTDX	74LVT162245MTDX	74LVT16373MTDX
74LVT16374MTDX	74LVT2244MTCX	74LVT244MTCX
74LVT245MTCX	74LVT373MTCX	74LVT573MTCX
74LVT574MTCX	74LVTH125MTCX	74LVTH162244MTX
74LVTH16646MTDX	74LVTH2244MTCX	74LVTH2245MTCX
74LVTH240MTCX	74LVTH244MTCX	74LVTH245MTCX
74LVTH373MTCX	74LVTH374MTCX	74LVTH573MTCX
74LVTH574MTCX	74LVX00MTCX	74LVX02MTCX
74LVX04MTCX	74LVX08MTCX	74LVX125MTCX
74LVX125MTCX_G	74LVX125SJX	74LVX132MTCX
74LVX138MTCX	74LVX138MX	74LVX14MTCX
74LVX157MTCX	74LVX161284MTDX	74LVX244MTCX
74LVX244SJX	74LVX245MTCX	74LVX273MTCX
74LVX3245MTCX	74LVX32MTCX	74LVX373MTCX
74LVX4245MTCX	74LVX541MTCX	74LVX573MTCX
74LVX74MTCX	74LVX86MTCX	74LVXC3245MTCX
74LVXC4245MTCX	74VCX00MTCX	74VCX08MTCX
74VCX162244MTDX	74VCX162373MTDX	74VCX16244MTDX
74VCX16245MTDX	74VCX163245MTDX	74VCX16373MTDX
74VCX16374MTDX	74VCX164245MTDX	74VCX245MTCX
74VCX86MTCX	74VHC00MTCX	74VHC00SJX
74VHC02MTCX	74VHC02MTCX_SF500910	74VHC02SJX
74VHC04MTCX	74VHC04SJX	74VHC08MTCX
74VHC08MTCX_SF500909	74VHC08SJX	74VHC112MTCX
74VHC112MX	74VHC123AMTCX	74VHC123AMX
74VHC123ASJX	74VHC125MTCX	74VHC132MTCX
74VHC138MTCX	74VHC138MX	74VHC138SJX
74VHC139MTCX	74VHC139MX	74VHC139SJX
74VHC14MTCX	74VHC14MTCX_SF500908	74VHC14SJX
74VHC153MTCX	74VHC153MX	74VHC157MTCX
74VHC157MX	74VHC157SJX	74VHC161284MTDX
74VHC161MTCX	74VHC161MX	74VHC161SJX
74VHC164MTCX	74VHC164SJX	74VHC175MTCX
74VHC175MX	74VHC175SJX	74VHC221AMTCX
74VHC221AMX	74VHC240MTCX	74VHC240SJX
74VHC244MTCX	74VHC244SJX	74VHC245MTCX
74VHC245SJX	74VHC273MTCX	74VHC273SJX
74VHC27MTCX	74VHC32MTCX	74VHC32SJX
74VHC373MTCX	74VHC374MTCX	74VHC393MTCX

Affected Product(s):

74VHC4040MTCX	74VHC4040MX	74VHC541MTCX
74VHC541SJX	74VHC573MTCX	74VHC573SJX
74VHC574MTCX	74VHC574SJX	74VHC595MTCX
74VHC595MX	74VHC595SJX	74VHC74MTCX
74VHC74MTCX_SF500950	74VHC74SJX	74VHC86MTCX
74VHCT00AMTCX	74VHCT04AMTCX	74VHCT08AMTCX
74VHCT138AMTCX	74VHCT14AMTCX	74VHCT240AMTCX
74VHCT240ASJX	74VHCT244AMTCX	74VHCT244ASJX
74VHCT245AMTCX	74VHCT245ASJX	74VHCT374AMTCX
74VHCT540AMTCX	74VHCT541AMTCX	74VHCT573AMTCX
74VHCT574AMTCX	74VHCT74AMTCX	74VHCU04MTCX
FAN47411MTCX	FAN47412MTCX	FAN5026MTCX
FAN5069EMTCX	FAN5069MTCX	FAN5234MTCX
FAN5236MTCX	FAN5236MTCX_NA3C246	FAN7318AMX
FAN7318PMX	FAN73402MX	FAN7340MX
FAN7621BSJX	FAN7621BSJX_G	FAN7621SJX
FAN7621SJX_G	FAN7621SSJX	FAN7621SSJX_G
FAN7631SJX	FAN7631SJX_G	FAN7688SJX
FAN77011MTCX	FAN77012MTCX	FAN9611MX
FAN9612MX	FIN1019MTCX	FIN1022MTCX
FIN1031MTCX	FIN1031MX	FIN1032MTCX
FIN1032MX	FIN1047MTCX	FIN1047MX
FIN1048MTCX	FIN1048MX	FIN1049MTCX
FIN1104MTCX	FIN1108MTDX	FIN1215MTDX
FIN1216MTDX	FIN1217MTDX	FIN1531MX
FIN1532MTCX	FIN1532MX	FIN3385MTDX
FIN3386MTDX	FMS6144AMTC14X	FMS6145MTC14X
FMS6146MTC14X	FMS6203MTC1406X	FMS6303MTC1406X
FMS6346EMTC20X	FMS6346MTC20X	FMS6364AMTC14X
FMS6403MTC20X	FMS6501AMTC28X	FMS6502MTC24X
FMS6646MTC20X	FMS6690MTC20X	FMS7000MTC14X
FSA2257MTCX	FSA2367MTCX	FSAL200MTCX
FSAV330MTCX	FSAV330MX	FSAV331MTCX
FSAV430MTCX	FSAV433MTCX	FSHDMI08MTDX
FSL8803MX	FSLV16211MTDX	FST16210MTDX_SB82221
FST16211MTDX	FST16233MTDX	FST16861MTDX
FST3125MTCX	FST3126MTCX	FST3244MTCX
FST3245MTCX	FST3253MTCX	FST3253MX
FST3257MTCX	FST3257MX	FST3345MTCX
FST3384MTCX	FST6800MTCX	FSTD16211MTDX

Affected Product(s):

FSTD16861MTDX	FSTD3125MTCX	FSTU32160MTDX
FSUSB11MTCX	FSUSB22MTCX	MM74HC00MTCX
MM74HC00SJX	MM74HC02MTCX	MM74HC04MTCX
MM74HC04SJX	MM74HC08MTCX	MM74HC08SJX
MM74HC125MTCX	MM74HC126MTCX	MM74HC132MTCX
MM74HC138MTCX	MM74HC138MX	MM74HC14MTCX
MM74HC14SJX	MM74HC164MTCX	MM74HC175MTCX
MM74HC175MX	MM74HC240MTCX	MM74HC240SJX
MM74HC244MTCX	MM74HC244SJX	MM74HC245AMTCX
MM74HC245ASJX	MM74HC273MTCX	MM74HC273SJX
MM74HC32MTCX	MM74HC373MTCX	MM74HC373SJX
MM74HC374MTCX	MM74HC374SJX	MM74HC540MTCX
MM74HC541MTCX	MM74HC541SJX	MM74HC573MTCX
MM74HC573SJX	MM74HC574MTCX	MM74HC574SJX
MM74HC595MTCX	MM74HC595MX	MM74HC595SJX
MM74HC74AMTCX	MM74HC74ASJX	MM74HC86MTCX
MM74HCT00MTCX	MM74HCT04MTCX	MM74HCT04SJX
MM74HCT05MTCX	MM74HCT05SJX	MM74HCT08MTCX
MM74HCT08SJX	MM74HCT138MTCX	MM74HCT138MX
MM74HCT14MTCX	MM74HCT240MTCX	MM74HCT244MTCX
MM74HCT244SJX	MM74HCT245MTCX	MM74HCT245SJX
MM74HCT273MTCX	MM74HCT273SJX	MM74HCT32MTCX
MM74HCT373MTCX	MM74HCT374MTCX	MM74HCT374SJX
MM74HCT540MTCX	MM74HCT541MTCX	MM74HCT573MTCX
MM74HCT574MTCX	MM74HCT574SJX	MM74HCT74MTCX
MM74HCU04MTCX	SLC1012CMX	SLC3012CMX
USB1T11AMTCX	USB1T20MTCX	