

Title of Change:	NTMFSS0D9N03P8 Pin Definition and Marking Change.
Effective date:	23 Aug 2023
Contact information:	Contact your local onsemi Sales Office or Rodrigo.Milana.Jr@onsemi.com
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.
Change Category:	Assembly Change
Change Sub-Category(s):	Datasheet/Product Doc change

Sites Affected:

onsemi Sites	External Foundry/Subcon Sites
onsemi Cebu, Philippines	None


Description and Purpose:

This split notification is issued to include OPN not specified in original PB25109X. This part is sharing same case outline 520AE from the previous PB25109X.


This Product Bulletin is issued to inform all impacted customers of the below affected PQFN 5x6 Source Down parts on the changes in their pin definition and marking (Pin 1 location) to standardize the Source Down package pin definition.

The below changes indicated will take place after the First Ship Date.

Before:



After:



No changes on the electrical performance of the affected parts are expected on above changes.

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

NTMFSS0D9N03P8		
----------------	--	--